

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Langlie Mattix Penrose Sand Unit Tract 33
8. Well No. 2
9. Pool name or Wildcat Langlie Mattix SR, Grbg

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Anadarko Petroleum Corporation
3. Address of Operator P.O. Box 806 Eunice, NM 88231
4. Well Location Unit Letter C : 330 Feet From The North Line and 2310 Feet From The West Line Section 33 Township 22S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) NA
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	PRESSURE READINGS ON TA'D WELL <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RUPU 9-17-87
2. TOH w/rods & tbq.
3. TIH w/wireline guage ring to 3400'.
4. TIH w/CIBP. Set appr. 3400' w/2 SX cement.
5. TIH w/CIBP. Set appr. 1200' on top of Anhydrite.
6. TIH w/7" PKR & tbq. Locate hole in csg.
7. TIH w/CIBP. Set appr. 100' above hole.
8. Pack off well head.
9. RDPU 9-22-87.

*NOTE: R.A. SADLER was on location to witness temporary abandonment.
2/22/90 Surface Casing Annulus Pressure 0#
2/22/90 Production Casing Annulus Pressure 0#

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Howard Hackett TITLE Field Foreman DATE 2/22/90
TYPE OR PRINT NAME Howard Hackett TELEPHONE NO. 394-3184

(This space for State Use)

ORIGINAL SIGNED BY STATE DEPARTMENT
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

FEB 26 1990

RECEIVED

FEB 23 1990

OCD
HOBBS OFFICE