Office

District I		-			WELL API	NO	···		٦
1625 N. French Dr., Hobbs, NM 87240 District II	OH CONSEDUA	OIL CONSERVATION DIVISION			30-025-10554				
811 South First, Artesia, NM 87210					5. Indicate Type of Lease				7
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco				STATE FEE x				
District IV	Santa Fe, NM 87505								
2040 South Pacheco, Santa Fe, NM 87505				_	6. State Oi	6. State Oil & Gas Lease No. 685270			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					7. Lease Name or Unit Agreement Name:				
PROPOSALS.)					Skelly Penrose 'A' Unit				
1. Type of Well: Oil Well Gas Well	Other Injection	Well							
2. Name of Operator					8. Well No).			1
Prize Operating Company							6		
3. Address of Operator					9. Pool name or Wildcat				
3500 William D. Tate, Suite 200, Grapevine, Texas 76051					Langlie Mattix 7-Rv Queen				
4. Well Location									
Unit Letter L	_980feet from the	Sou	ıth	line and	660	feet from	the Wes	t line	e
Section 33	Township 22	2S	Range	37E	NMPM		County	Lea	
	10. Elevation (Show wh	hether	DR, RKE	3, RT. GR, etc	c.)				Ş
		33	32' GR						
11. Check Ap	propriate Box to Ind	licate	Nature	of Notice,	Report, or	Other I)ata		
NOTICE OF INTENTION TO: SUBSEQUENT RE						T REP	ORT OF		
	PLUG AND ABANDON		REMEC	DIAL WORK	OLGOLI		ALTERING (CASING	Γ
	. 2007			on the violation		ш	ALILINIO	JAJING	L
TEMPORARILY ABANDON X	CHANGE PLANS		соммі	ENCE DRILL	LING OPNS. PLUG AND ABANDONMEN		AENT.		
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING CEMEN	G TEST AND IT JOB					
OTHER:			OTHER	!:					
12 Describe Donners des Consulter 1	0 1 (01 1	11		1					_

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

Prize Operating Company respectfully requests approval to Temporarily Abandon the well by the following procedures as prescribed by the Oil Conservation Division.

- 1. MIRU service unit and pull out of hole with tubing and packer.
- 2. RIH with CIBP and set at approximately 3500'. (current perfs 3564-3652')
- 3. Test CIBP and casing to 500 psi.
- 4. RD and move off wellbore. Leave well TA'd.

I hereby certify that the information above is true and complete to the SIGNATURE COLOR COLOR	best of my knowledge and belief. TITLE Regulatory Analyst	DATE_	12-6-2001
Type or print name Don Aldridge		Telephone No.	817-424-0454
(This space for State use)			
APPROVED BY	TITLE	DATE	office a confi

Prize Operating Company

UPDATE 11-29-01 CURRENT COMPLETION

WELLBORE DATA AND SKETCH

