

NEW MEXICO OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work is begun. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

NOTICE OF INTENTION TO TEST CASING SHUT-OFF		NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL	
NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING	
NOTICE OF INTENTION TO REPAIR WELL		NOTICE OF INTENTION TO PLUG WELL	XX
NOTICE OF INTENTION TO DEEPEN WELL			

Hobbs, New Mexico
PlaceMarch 25, 1949
DateOIL CONSERVATION COMMISSION,
Santa Fe, New Mexico.

Gentlemen:

Following is a notice of intention to do certain work as described below at the _____
Skelly Oil Company H. O. Sims Well No. 16 in SW/4 SW/4

 Company or Operator Lease
 of Sec. 34, T. 22S, R. 37E, N. M. P. M., Drinkard Field.
Lea County.

FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

Well drilled to total depth of 6650', no oil, gas or water encountered in Drinkard section. Plugged back to 3670' and tested Queens Sand section which likewise was barren of oil, gas or water - DRY HOLE - Will be plugged and abandoned in accordance with rules and regulations of the New Mexico Oil Conservation Commission as follows:

Will spot 50 sacks cement at 6650' then fill hole with heavy mud laden fluid to 5140'. Will spot 50 sacks cement at 5140' and fill with heavy mud laden fluid to 3850'. Will spot 120 sacks cement at 3850' and fill with heavy mud laden fluid to 3525'. Will spot 20 sacks cement at 3525' then fill with heavy mud laden fluid to 2700' (8-5/8" casing set at 2800' & cemented to surface) Will spot 20 sacks cement at 2700' and then fill with heavy mud laden fluid to 50'. Will then fill to surface with 15 sacks cement, install cement cap and 4" pipe marker.

Confirming oral approval given by Mr. Roy Yarbrough to J. N. Dunlavy.

Approved MAR 29 1949, 19____
 except as follows:

Skelly Oil Co.

 Company or Operator
 By J. N. Dunlavy
 Position District Superintendent
 Send communications regarding well to
 Name Skelly Oil Co.
 Address Drawer "D"
Hobbs, New Mexico

OIL CONSERVATION COMMISSION,
 By Roy Yarbrough
 Title Oil & Gas Inspector

1000 2000 3000 4000 5000 6000 7000 8000 9000 10000