## State of New Mexico rgy, Minerals and Natural Resources Departm.

Form C 103 Revised 1-1-89

District Office		-			
DISTRICT I P.O. Box 1980, Hobbs, NM S8240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.		
P.O. Box 1980, Hobbs, NM 58240			30-025-10712		
P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico	5. Indicate Type of Lease STATE FEE			
DISTRICT T11 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Ga		
SUNDRY NOTICES AND REPORTS ON WELLS  ( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE *APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
1. Type of Well: Oil Well Well Well	OTHER	State A A/C 1			
2. Name of Operator Raptor Resources, Inc.			8. Well No. 79		
3. Address of Operator	1000, mo.		9. Pool name or V		
901 Rio Grande, Austin, TX 7	8701		Jalmat, Tnsl, Y	ts, 7-Rivers (Pro G	as) (79240)
4. Well Location Unit Letter E 1980	Feet From The North	Line and 66	O Feet From	1 The West	Line
Section 14	Township 23S Ra	ange 36E	NMPM	Lea	County
///////////////////////////////////////	10. Elevauon (Show whether	DF, RKB. RT, GR, ctc.)		///////////////////////////////////////	////////
Check A	Appropriate Box to Indicate	Nature of Notice, Re	eport, or Other	r Data	
NOTICE OF INTENTION TO:			SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	$\boxtimes$	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS	OPNS.	PLUG AND ABAND	ONMENT L	
PULL OR ALTER CASING		CASING TEST AND CE	MENT JOB		
OTHER:		OTHER			
12. Describe Proposed or Completed Opwork)SEE RULE 1103.					
7-20-99 MIRU. GIH to PBTD @ 33 3035-3036, 3041-3043, 3046-3048, 3 3140-3143 & 3150-3153 for a total of annulus to 500#, broke formation @ ons CO2 carrying 191,880# 12/20 B 7-24-99 GIH W/ 2 3/8" tbg set @ 316 7-25-99 RDMO. 8-1-99 Test: 0 oil, 5 b/w, 345 M	3064-3065, 3078-3079, 3084-308 of 59 holes. Set packer @ 3150'. 1300#. Acid perfs W/ 1800 gal 1 rady sand in 6 stages. Released p 64' and 1 1/16"X12" Texas Stripp	6, 3088-3090, 3094-309 Spot 200 gal acid acros 5% HCl W/ 100 ball se backers, POOH. Clean	ss perfs. Set pack alers. Frac W/5 out sand fill to F	ker @ 2860'. Press 2,250 gal 40# line:	ure
12. I hereby certify that the information above is trusting signature Signature Bill R. Keathly	e and complete to the best of my knowledge and		ent for Raptor	DATE 9-(	5-99 5-697-1609
(this space for State Use) ORIGINAL	SOINED BY			OCT 05 1	999
APPROVED BY	: R <b>≜P</b> #	Е		DATE	
CONITIONS OF APPROVAL, IF ANY:			- 5		