ENERGY AND MINERALS DEPARTMENT	
CONSERVATION DIVISIO	F 6 300
DISTRIBUTION P. O. BOX 2088	Form C-103 . Revised 10-1-78
SANTA FE, NEW MEXICO 87501	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
TILE	5a. Indicate Type of Lease
U.S.G.S.	State Foe XX
LAND OFFICE	5. State Ott & Gas Lease No.
OPERATOR	
	mmmmm
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PADPOSALS TO DAILL OR TO DEEPEN OR PLUS BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
(DO NOT USE THIS FORM FOR PADPOSALS TO DRILL OF TO DRILL OF TO SUCH PROPOSALS.)	7. Unit Agreement Name
1. OIL 649 []	7. 61
WELL X WELL OTHER-	8. Farm or Lease Name
2. Name of Operator	Edith Butler
American Petrofina Co. of TX	9. Well No.
3. Address of Operator	5
P. O. Box 1311 Big Spring, TX 79720	
4. Location of Well	10. Field and Pool, or Wildcat
F 1980 N 1980 HHIT LETTER FEET FROM THE LINE AND FEET FROM	Drinkard
UNIT LETTER FEET FROM THE LINE AND FEET FROM THE	
THE W LINE, SECTION 18 TOWNSHIP 22-S NAME 38-E NAMPM.	
THE W LINE, SECTION LO TOWNSHIP LE D MANUE	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
+ 3353 (DF)	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Other	per Data
• • • • • • • • • • • • • • • • • • • •	REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUENT	NEI OILI OI
PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMODIAL WORK	PLUG AND ABANDONMENT
TEMPORANILY ADANDON COMMENCE DRILLING OPNS.	
PULL OR ALTER CASING CASING TEST AND CEMENT JOS	. [
отиея	
OTHER	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.	
The Plinchry (Perf 5628-5718)	
This well is presently producing from the Blinebry (Perf 5628-5718).	
	nkard
It is proposed to temporily abandon the Blinebry - perforate the Dri	·
zone from 6410 to 6815 and test.	
•	

FEB 28 1983
HOBBS OFFICE