

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPT
(Other instruction,
reverse side)

TE*
FO*

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

BLINEBRY

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A. H. Blinebry Fed. NCT-1

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

Blinebry

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 19, T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. WELL	<input checked="" type="checkbox"/> GAS WELL	<input type="checkbox"/> OTHER
2. NAME OF OPERATOR TEXACO Inc.		
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Well is located 1980' from the North Line and 1974' from the East Line of Section 19, T-22-S, R-38-E, Unit Letter G, Lea County, New Mexico.		
14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3378 (DF)	

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Well Shut in

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

In an attempt to repair communications between the Blinebry and Tubb zones found 2-7/8" tubing parted @5690'. Recovered 18' to 5708', unable to pull remainder of tubing and packer @6105'.

Ran 2-7/8" tubing w/packer and set @5702' to produce the Tubb zone.

The status of the Blinebry was changed from flowing to TR-0, effective March 4, 1970. This well is being held for remedial work.

18. I hereby certify that the foregoing is true and correct

SIGNED

Assistant District Super-
intendent

DATE March 6, 1970

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 9 1970

*See Instructions on Reverse Side
GEOLOGICAL SURVEY
HOBBS, NEW MEXICO