NO. OF COMIES PECCIVED		-	Form C-		
DISTRIBUTION			Supersee		
ANTA FE	NEW MEXICO OULC	ONSERVATION COMMISSION		C-102 and C-103 Effective 1-1-65	
ILE			Buch	- • • • • •	
			Sa Indicate	Type of Lease	
1.5.G.S.			1 r-		
AND OFFICE			State	Fre C	
PERATOR			5. State GII	& Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS					
TOO NOT USE THIS FORM FOR PROCESSES TO DRIVE ON TO CAPPEN ON PROCESSES TO A DIFFERENT RESERVOIR. USE TAPPEICATION FOR PERMIT AT TROOP, C-101, FOR SIGH PROPERTY.				Allilililililili	
	And the second track that the second property of the second track the second track the second track the second	eri ere ere insere zur einserialische im die deutsche zugen ere erenden zugenzung zur zugen zu gestellt. Die d	7. Unit Agre	N.N.X.X.N.X.X.X.X.X.X.X.X.X.X.X.X.X.X.X	
OTE X SAS WELL	eruse.				
Name of Operator	отиея-		0 5000000		
·			i i	6. Form or Lease Name	
Gulf Oil Corporation			Evelyn	Evelyn Linebery	
Address of Operator			9. Well No.	9. Well No.	
P. O. Box 670, Hobbs, New Mexico 88240				2	
Lecation of Well				10. Field and Pool, or Wildest	
1000 660			į.	i i	
UNIT LETTER L . 1980 FERT FROM THE SOUTH LINE AND 660 FEET FROM				Blinebry	
THE West LINE, SECTION 29 TOWNSHIP 22-S, RANGE 38-E NMP				//////////////////////////////////////	
	15. Elevation (Show when	ther DF, RT, GR, etc.)	. 12, County		
		3388'	Lea		
771177777777777777777777					
Chec	k Appropriate Box To Indicat	e Nature of Notice, Report	or Other Data		
NOTICE OF	INTENTION TO:	suase	QUENT REPORT	OF:	
		· ·			
REGRIA REMEDIAL WORK	PEUG AND ABANDON	REMEDIAL WORK	· ,	LTERING CASING	
<u> </u>		- 1	-		
MFCRARILY ABANDON	ſ	COMMENCE DRILLING OPNS.	Pi	THEMHODHARA DHA DU	
LE OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB			
	,	OTHER Clean out 8	x acidize		
OTHER					
Describe Proposed or Completed work) SEE RULE 1103.	Operations (Clearly state all pertinent	details, and give pertinent dates, in	scluding estimated date	of starting any propose	
ana) see Noce 1103.					
• .					
5874¹ PB.					
		·			
Pulled producing	agui mmont				
Class out fill for	=quipment.				
Clean out fill fro					
	0 gallons 2% NE acid.	•			
Run producing equi					
Returned well to	production.				
•	`				
				•	
•					
	•				
I hereby certify that the information	on above is true and complete to the be-	et of my knowledge and belief			
and the second transfer and trans		er my knowledge and belief.			
ro	TITLE	Area Engineer	DATE	1-27-77	
				The state of the second st	
(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)		·		*1 h 7 * \$	
	e e e e e e e e e e e e e e e e e e e			. 19//	
OVED BY	TITLE		41477		

DITIONS OF APPROVAL, IF ANYI

OIL CONSERVATION COMM.