

SHEET 2

A.H. Blinbry Fed. NCT-1

Well No. 3

Lea County, New Mexico

19. Set CIBP @ 6700' w/30' cement on top of plug. PBTD 6670'.
20. Perforate 7" OD csg w/2 JSPF @ 6394', 6400', 37', 64', 79', 85', 96', 6514', 30', 53', 86', & 6627'.
21. Spot 500 gal. 15% NE Acid over perforations 6394'-6627'. Set pkr @ 6282'. Acidize w/2000 gal 15% NE Acid.
22. Frac 7" csg perforations 6394'-6627' w/40,000 gal water containing 50,000# 20/40 sand in 2 equal stages using 12 ball sealers between stages.
23. Install pumping equipment. On 24 hr Potential Test, Drinkard Zone pumped 64 BO & 19 BW. GOR 3125.

RECEIVED

MAR 1 1977

LIBRARY OF CONGRESS