Form 9-331 (May 1963)	DEPAF		HE INTERI	SUBMIT IN TRIP (Other instruction verse side)	PLICATE• ns on re	LEASE DESIG	approved. et Bureau No. 42			
GEOLOGICAL SURVEY SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)							6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
I. OIL X GAS WELL OTHER							7. UNIT AGREEMENT NAME			
2. NAME OF OPERATO				· · · · ·		8. FARM OR LE	ASE NAME			
TEXACO I 3. ADDRESS OF OPER		·····				A.H. 9. WELL NO.	Blinebry	y Fed.	NCT-	
P. O. Bo	х 728, н	lopus, New	Mexico	88240		5. WELL NO.			2	
P. 0. Box 728, HODDS, New Mexico 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface Well is located 060' FSL & 660' FWL							10. FIELD AND FOOL, OR WILDCAT			
of Section 29, T-22-S, R-38-E, Unit Letter 'M',						Blinebry Gas				
Lea County, New Mexico						11. SEC., T., R., M., OR BLK, AND SUBVEY OR ABEA Sec. 29, T-22-S,				
						R-30-E	رS-22-5 و			
14. PERMIT NO.	<b>-</b>	15. ELEVATIONS	(Show whether DF,	, RT, GR, etc.)			PARISH 13. STAT	TE		
Regu			<u>3390' (D</u>	· · · · · · · · · · · · · · · · · · ·		Lea	New	Mexico	C	
16.	Check	Appropriate Box	To Indicate N	ature of Notice, Repo	ort, or O	ther Data				
	NOTICE OF IN					ENT REPORT OF:				
TEST WATER SHI	UT-OFF	PULL OR ALTER CA	SING	WATER SHUT-OFF		REPA	IRING WELL			
FRACTURE TREAT		MULTIPLE COMPLE	те	FRACTURE TREATME	INT	ALTE	RING CASING			
SHOOT OR ACIDIZ	E	ABANDON*	<u>_X_</u>	SHOOTING OR ACIDI	ZING	ABAN	DONMENT*	_		
(Other) *B7	ineprv G	CHANGE PLANS	x	(Other)(NOTE: Report	rt results o	of multiple com	letion on Well			
17. DESCRIBE PROPOSE	D OR COMPLETED	OPERATIONS (Clearly	state all pertinent	(NoTE: Repor Completion or details, and give pertine ions and measured and tri	r Recomple	tion Report and	Log form.)			
proposed work. nent to this wor	If well is dire k.)*	ectionally drilled, give	subsurface locati	ions and measured and tra-	ue vertical	depths for all	ted date of starti markers and zone	ng any s perti-		
Please o	cancel No	otice of Ir	tention	(Form 9-331)	filed	l with US	SGS,			
January	15, 1976	5 & approve	ed by you	r office Janu	arv 2	0. 1976.	to			
Abandon	pr ment.	Gas & rec	complete a	subject well	in th	e Drinka	ard			
Zone.										
									•	
									-	
	r.									
8. I hereby certify th	at the foregoing	is true and correct								
SIGNED	<u> </u>	1-2 62	TITLE A	sst. Dist. S	upi.	. DATE	6-21-76	5		
(This space for Fe	deral or State o	office use)								
					<b></b>			7		
APPROVED BY CONDITIONS OF	APPROVAL, IF	ANY:	TITLE			APPR-	OVFD			
						43 I I <b>I V</b>	- T Na 50			
						JUN X	4,1976	1		
		*Se	e Instructions o	on Reverse Side		DEDNADD	MODOZ			
						BERNARD	MOROZ ICT ENGINEF*	1		
					-nC		ICT LINGINF'			