

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 032104

Unit \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO <del>REPAIR</del> ACIDIZE	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Midland, Texas, March 17, 1948

A. H. Blinbry

Well No. 5 is located 660 ft. from S line and 660 ft. from W line of sec. 29

SW 1/4  
(1/4 Sec. and Sec. No.)

22-S  
(Twp.)

38-E  
(Range)

NMPM  
(Meridian)

Drinkard  
(Field)

Lee  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3390 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD: 7120 - Lime

This well was completed for 295 barrels pipe line oil in 8 hours, April 29, 1947, at total depth 7120. Production has declined to 64 barrels oil, 3% water per day. GOR-8000. This well has been penalized to 20 barrels per day (March proration schedule).

In an effort to reduce the GOR, tubing has been pulled and rerun with packer set at 6960, well swabbed 90 barrels fluid, 10% water in 10 hours.

We now desire to acidize with 3000 gallons 15% western to test this section for production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company The Texas Company

Address Box 1270, Midland, Texas

By

Title District Superintendent