		STATES BUBMIT IN THE INTERIOR Verse alde)	tetion no.	Expires Au	ved. emu No. 1004-013; gust 31, 1985 THON AND SHELAL NO.
	NDRY NOTICES AN	D REPORTS ON WELLS r to deeper or plug back to a different re ERMIT- for such proposals.)			OTTER OR TRIBE NAME
I. OIL GAS WELL WELL	OTHER			UNIT ACCOUNTS	TRANS
NAME OF OPERATOR				8. PARM OR LEASE HAME	
Texaco Inc.				A. H. Bli	nebry Fed NC
P. O. Box 728 LOCATION OF WELL (F See also space 17 belo At surface	8, Hobbs, NM 88240 Report location clearly and in a low.)	accordance with any State requirements.*	10	13 Drinkard	OR BLK. AND
2310' FNL & 3	330' FWL				inna.
4. PERMIT NO. 15. ELEVATIONS (Snow whether DF, BT, GR, etc.)				Sec 29, T22S, R38E	
	3	375' G.L.		LEA	NM
6. I	Check Appropriate B	lox To Indicate Nature of Notice,		RAPORT OF :	
TEST WATER SHUT-OF	PULL OR ALTER	CASINE WATER SHUT-			[]
FRACTURE TREAT	MULTIPLE COM				G CABING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OF	ACIDIZING	ABARDON	MENT.
REPAIR WELL (Other)	CHANGE PLANS		ill out CIB Report results of 1		
DESCRIBE PROPOSED OR	COMPLETED OPERATIONS (Clear	rly state all pertinent details, and give per give subsurface locations and measured and	on or Recompletio	a Report and Le	form.)
	production equipme commingle Blinebry	ent. y oil & gas and Drinkard	pools.		
			REC	EIVE	3
				EIVE	3
				EIVE 24 1986	3
				24 1986	
I baraby souther that t		9 .1	JUL ;	24 1986	
I bereby certify that t SIGNED	the specoing is true and corre		JUL ; Hobbs, N	24 1986 Ew Mexic	
11/	al or State office use) m M. Comuch PROVAL 15 ANY:	ect	JUL ; Hobbs, N	24 1986 Ew Mexic	70 7 8, 1986





· · · · · ·

STAR CHANNESS SCH

CAN PLAN