

Submit 3 Copies To Appropriate District

Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO.

30-025-12157

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Drinkard NCT "B"

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Chevron USA, Inc.

8. Well No.

2

3. Address of Operator 15 Smith Rd. Midland, Tx 79705

9. Pool name or Wildcat

Drinkard Blinebry

4. Well Location

Unit Letter J : 1980 feet from the south line and 1980 feet from the East line

Section 30 Township 22-S Range 38-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 7" CIBP @ 5550, spot 25sx plug 5550-5450(Blinebry)Tag @ 5428
2. Displace hole w/MLF, 9.5# Brine w/25sx Gel P/BBL.
3. Spot 40sx plug 3600-3400(Queen)
4. Spot 55sx plug fr/3000-2700(9 5/8 shoe, B-salt) Tag @ 2687
5. Perf 4 holes @ 1400,sqz perf w/100sx fr/1400-1200(T-salt)Tag @ 1220
6. Perf 4 holes @ 365, circ cmt fr/365 to surf w/195sx (13 3/8)csg Tag @ surf
7. Install dry hole marker 10-31-02

Approved as to plugging of the Well Bore
Liability until is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Bagley TITLE MANAGER/SUNSET DATE 10-31-02

Type or print name Jimmy BAGLEY Telephone No. 915520-8756
(This space for State use)

APPROVED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE FEB 17 2003

Conditions of approval, if any:

GARY W. WINK

OC FIELD REPRESENTATIVE II/STAFF MANAGER

GWW

2