STATE OF NEW MEXICO ERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION ---Form C-103 -DISTRIBUTION P. O. BOX 2088 Revised 10-1-78 SANTA FE, NEW MEXICO 87501 SANTA FE FILE 5a. Indicate Type of Lease U.S.G.S. State Foo X LAND OFFICE 5. State Oil & Gas Lease No. OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFE USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.) 7. Unit Agreement Name SIL X OTHERime of Operator 8. Farm or Lease Name Drinkard (NCT-B) Chevron U.S.A. Inc. 9. Well No. idress of Operator P.O. Box 670 Hobbs, NM 88240 10. Field and Pool, or Wildcat egtion of Well South 1980 Blinebry 1980 UNIT LETTER **22S** 12. County 15. Elevation (Show whether DF, RT, GR, etc.) 33541 Lea GL Check Appropriate Box To Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING PLUS AND ABANDON PLUG AND ABANDONMEN PORARILY ABANDON CASING TEST AND CEMENT JOB CHANGE PLANS TA Tubb Recondition Blinebry Durkand

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Sot CIRD 3 6250' and can with 35' of cement. Add Rlinebry perforations 5746'-5820'.

Set CIBP @ 6250' and cap with 35' of cement. Add Blinebry perforations 5746'-5820'. Acidize and fracture treat as necessary. Equip for production. Return to production as a single producer in the Blinebry.

. Division Drilling M	lanager 9-10-1986
Orig. Signed by Paul Kautz Geologist	SEP 1 2 1986