

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rm Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-12184
5. Indicate Type of Lease	STATE ☐ FEED ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	7. Lease Name or Unit Agreement Name T.R. Andrews
4. Well Location Unit Letter <u>J</u> : 1980 Feet From The <u>South</u> Line and 1980 Feet From The <u>East</u> Line Section <u>32</u> Township <u>22S</u> Range <u>38E</u> NMPM Lea County	8. Well No. <u>3</u>
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3398' GL	9. Pool name or Wildcat Blinebry

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Resqueeze Paddock & Acidize Blinebry ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1101.

MIRU PU, TOH W/ PUMP & RODS NUBOPE TOH W/ 2 3/8" PROD TBG TIH WL 4 3/4" BIT & CSG
SCRAPER TAGGED @ 5999 TOH TIH W/ RBP & PKR ISOLATE CSG LK IN OLD
PADDOCK PERFS 5164-5216 EST INJ RATE TOH W/ PKR TIH & SET CICK @ 5092 & SQZ
PADDOCK PERFS W/ 75 SX CL "H" CWL LEAD + 75 SX CL "H" CWL TAIL CMT ACHIEVED 3000
PSI, SQZ REV OUT 27 SXS TOH W/ BIT DO CICK & CMT F 5084 TO 5223, TST SQZ & CSG
TO 500 PSI 20 MIN W/ NO LEAKOFF, TIH W/ PKR & SET @ 5595 ACDZ BLINEBRY PERFS
5664 TO 5899 W/ 3000 GALS 15% NEFE HCL & 36 - 7/8", 1.1 SPGR RCNBS AIR-4 BPM
PMAX-1150 W/ GOOD BALL ACTION 5 HR SWB TST REC'D 62 BW & SPENT ACID SFL-4000
EFL-5380 FER-10.8 BPH BLWTBR-59, TOH LD WS & PKR TIH W/ 2 3/8" PROD TBG EOT @
5948 SN @ 5911 TAC @ 5144 NUWH TIH W/ PUMP & RODS CHECK PUMP ACTION TO 500 PSI
OK RDMO PU TURN OVER TO PRODUCTION.

WORK STARTED 3-14-90 WORK ENDED 3-22-90

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. E. Akins 3/23/90 TITLE Staff Dir. Engr DATE 3-23-90

TYPE OR PRINT NAME M.E. Akins

TELEPHONE NO. 393-4121

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE MAR 27 1990

CONDITIONS OF APPROVAL, IF ANY: