

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-12186
2. Name of Operator Chevron U.S.A. Inc.	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P.O. Box 1150 Midland, TX 79702	6. State Oil & Gas Lease No.
4. Well Location Unit Letter A : 560 feet from the NORTH line and 660 feet from the EAST line Section 32 Township 22S Range 38E NMPM County LEA	7. Lease Name or Unit Agreement Name: T. R. ANDREWS
8. Well No. 5	
9. Pool name or Wildcat TUBB OIL & GAS (OIL)	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: PB <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

POH W/PROD EQPT. SET CIBP @ 5300'. FOUND CSG LEAKS. PUSHED CIBP TO 6581'. PPD
150 SX CMT; PRESS TBG TO 1000 PSI - OK. TOC @ 5005'. DO CMT TO 5265'. WASHED
TO 5474', DRLD OUT REP. CIRC CLEAN. SET CIBP @ 6360'. PERFD 5998'-6292'
W/4 JHPF. DUMPED 4 SX CMT ON CIBP (20'). ACZD W/5000 GALS 15% & 160 RCNB'S.
SWABBED. FRACD W/60,696 GALS PAD & 144,176# SAND. CO W/TOIL TBG UNIT TO 6330'.
CIRC CLEAN. SWABBED. RIH W/TBG, PUMP & RODS; TBG @ 5929'. RETURNED WELL TO
PRODUCTION.

WORK PERFORMED 12/12/00 - 1/25/01

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J.K. Ripley TITLE REGULATORY O.A. DATE 2/19/01

Type or print name J. K. RIPLEY Telephone No. (915) 687-7148

(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____

Conditions of approval, if any:

2A Paddock South