

1980

Designate UNIT well is located in

D	C	B	A
E	F	G	H
L	K	J	I
M	N	O	P

DATE STARTED 7-21-47
DATE COMPLETED 12-7-47
ELEVATION 5398
TOTAL DEPTH S.L. 8063 FBTD 7245
CABLE TOOLS ROTARY TOOLS **X**

SIZE	18-3/8	DEPTH	281	SAX CEMENT	310
SIZE	7-5/8	DEPTH	3000	SAX CEMENT	900
SIZE	5-1/2	DEPTH	6881	SAX CEMENT	150

SIZE 2 1/2 DEPTH 6928

NO. GALS.	<u>500</u>	<u>11-13-47</u>
NO. GALS.	<u>2500</u>	<u>11-15-47</u>
NO. GALS.	<u>4000</u>	<u>11-25-47</u>

NO. QTS. None
NO. QTS. _____
NO. QTS. _____

Rustler	Anhydrite	1360
	Top Salt	
	Base Salt	2530
Glorieta	Red Sand	5190
Tabbs	Black Oil	6070
	White Lime	
	Oil or Gas Pay	6920
	Water	

PIPE LINE TAKING OIL

SIGNED BY: Kees Z Hendrickson

Form 2-77

DATE

To: H. M. O. C. C. Floor No.

Remarks: Letter, H. M.

From

Handwritten signature

Place Hobbs, New Mexico
Date December 8, 1947

Glenn Staley
Proration Office
Hobbs, New Mexico

Designate UNIT well is located in
K

D	C	B	A
E	F	G	H
L	K	J	I
M	N	O	P

NOTICE OF COMPLETION OF: (Lease) State "T" Well NO. 1
1980 feet from West line: 1980 feet from South line;
Section 32 Township 22-S Range 38-E.

DATE STARTED 7-21-47
DATE COMPLETED 12-7-47
ELEVATION 5398
TOTAL DEPTH S.L. 8063 FBTD 7845
CABLE TOOLS _____ ROTARY TOOLS X

CASING RECORD

SIZE	<u>13-3/8</u>	DEPTH	<u>281</u>	SAX CEMENT	<u>310</u>
SIZE	<u>7-5/8</u>	DEPTH	<u>3000</u>	SAX CEMENT	<u>900</u>
SIZE	<u>5-1/2</u>	DEPTH	<u>6881</u>	SAX CEMENT	<u>150</u>

TUBING RECORD

SIZE 2" DEPTH 6928

ACID RECORD

NO. GALS. 500 11-12-47
NO. GALS. 2500 11-15-47
NO. GALS. 4000 11-25-47

SHOT RECORD

NO. QTS. None
NO. QTS. _____
NO. QTS. _____

FORMATION TOPS

<u>Rustler</u>	Anhydrite	<u>1360</u>
	Top Salt	
	Base Salt	<u>2550</u>
<u>Glorieta</u>	Bed Sand	<u>5190</u>
<u>Tabbs</u>	Superficial	<u>6070</u>
	White Lime	
	Oil or Gas Pay	<u>6920</u>
	Water	

Initial Production Test _____ Pumping _____ Flowing X
Test After Acid or Shot 52 BOPD on 16/64" choke. GOR 2295.

Initial GAS VOLUME 120 MCF per day.

SCHEDULE NO. _____ DATE _____

PIPE LINE TAKING OIL _____

REMARKS _____ COMPANY STANOLIND OIL AND GAS COMPANY

SIGNED BY: Robert Henderson

Form 5-47

DATE

To: H. M. O. C. C. Floor No.

Remarks: Letter, H. M.

From

[Handwritten signature]