NUMBER OF COP .S RECEIVED			NEW MEALOUR CONSERVATION COMMISSION	(Form C-16)
IANTA (F.C.)			Santa Fe, New Mexico	Pavised 7/1/57
			REQUEST FOR (OIL) - (GAS) ALLOWARLE	3
TRANSPORTER	01L 6A8			•
PREATION OFFICE	k			New Well Recompletion
~ ~		when sted	by the operator before an initial allowable will be assigned to any completed	•
			QUADRUPLICATE to the same District Office to which Form C-101 was	
			0 A.M. on date of completion or recompletion, provided this form is filed	
			etion. The completion date shall be that date in the case of an oil well wh	
red into th	ne stock ta	nks. Gat mu	ist be reported on 15.025 psia at 60° Fahrenheit. TEXACO Inc 1	
			Hobbs, New Mexico Mar (Place)	(Date)
VE ARE F	EREBY	REOUEST	ING AN ALLOWABLE FOR A WELL KNOWN AS:	(,
		-	H. Blinebry NCT-1 , Well No. 15 , in NW	VA NW VA
D	, Se	<u></u>	T. 22-S, R. 38-E, NMPM., Undesignated (Dri	nkard) Pool
Unit Le	Lea		County Date Spudded Jan. 18, 1962 Date Drilling Completed	Feb. 12. 1962
••••••	•••••		Elevation 3384 (DF) Total Depth 7242 PBTD	None
Pleas	se indicate	location:	Top 011/Gas Pay 6908' Name of Prod. Form. Drinka:	
D	CE	A		L'U
x			PRODUCING INTERVAL -	
Е	F G	H	Perforations See Attached Sheet Depth 70401 Depth	
			Open HoleCasing Shoe7240 *Tubing	72401
			OIL WELL TEST -	
L	K J		Natural Prod. Test:bbls.cil,bbls.water inhrs	Choke min, Size
			Test After Acid or Fracture Treatment (after recovery of volume of oil e	
<u>M</u>	N O	P	load oil used): 25 bbls.oil, 0 bbls water in 24 hrs,	
	L		GAS WELL TEST -	
			Natural Prod. Test:MCF/Day; Hours flowedChok	e Size
tubing ,Cas		menting Reco	Method of Testing (pitot, back pressure, etc.):	
Size	Fret	Sax		s flowed
0 = (0)	1.000	-	Choke Size Method of Testing:	
8-5/8"	1339	700		
2-3/8"	7229	*1200	Acid or Fracture Treatment (Give amounts of materials used, such as acid,	water, oil, and
			sand): See Below	
2-7/8"	6853	*1200	Casing Tubing 100 Date first new March 5, 19 Press Press. 100 oil run to tanks March 5, 19	62
	1		Oil Transporter Texas New Mexico Pipe Line Comp	any
			Gas Transporter Skelly Oil Company	
lemarks:	*Both	strings		
	See A	ttached	require 1200 sx.	5thel
				1
• • • •			it is the state of an explore to the best of my knowledge	
1 hereb	by certify i	that the init	ormation given above is true and complete to the best of my knowledge.	
pproved	$\overline{}$, 19, 19	
al-			COMMISSION By: 73777784	,
	L CONSE	LAVA HON	COMMISSION By: (Signature)	
1/1	1/1		Title Assistant District Supe	rintendent
¥	\sim ()		Send Communications regarding	well to:
ïtle		<i>C</i>	NameH. N. Wade	· *

ت

Address Box 728 - Hobbs, New Mexico

.]

Ran Correlation Log and perforate 2-3/8" OD casing 6908' to 6910', 6932' to 6936', 6950' to 6954', 6962' to 6964', 6988' to 6993', 7017' to 7020', 7062' to 7064', 7132' to 7134' and 7170' to 7174' with 1 Jet shot per ft. Spot acid over perfs. Acidize with 3000 gals LST NEA at .35 BPM. Re-acidize perfs with 6000 gals LST NEA in 3-2000 gal stages with 100 gals Temp blocking material between stages and before 1st stage at 4 BPM. Re-acidize perfs with 12,000 gals LST NEA at 4.4 BPM.