

* = please attach pertinent documents

I. OPERATOR / LOCATION INFORMATION

Operator Enbridge
Address Box 1137
Enbridge N.W. 8331 Phone 505 334-2511
Well unit # 1 Location Box 1137
T. 1 R. 1 Sec. 1 1/4 1/4 1/4
County Lincoln
Purpose of well (brine supply, LPG storage, potash dissolution) Brine supply

II. DRILLING / SITING INFORMATION

Contractor SK-114
Date drilling started Feb 1955 Date drilling completed Feb 1955
Drilling method Hydraulic (open hole)
Elevation of ground surface 1020 How measured Survey
Date measured 1955 Order of survey 1
Name of surveyor 1
Total depth of hole 2045' BGL

Attach schematic of well, include open hole interval, perforations, etc. *

Type of drilling fluid Water
Type of drilling mud if used (brand if known) Water

List any additives to the drilling mud, or any other chemicals put down well:

Describe casing tests performed 11-11-55

Other tests 11-11-55

ILLEGIBLE