

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION  
 DIVISION OFFICE O. C. C.  
 JUN 11 4 30 PM '69

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-4467-1</b>

### SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>Dual</b>	7. Unit Agreement Name
2. Name of Operator <b>Gulf Oil Corporation</b>	8. Farm or Lease Name <b>T. R. Andrews</b>
3. Address of Operator <b>Box 670, Hobbs, New Mexico 88240</b>	9. Well No. <b>6</b>
4. Location of Well UNIT LETTER <b>H</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>32</b> TOWNSHIP <b>22-S</b> RANGE <b>38-E</b> NMPM. <b>So. Paddock &amp; Blinebry</b>	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) <b>3381' GL</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

#### NOTICE OF INTENTION TO:

#### SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER <b>Abandon Blinebry Zone</b>			

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**5870' TD, 5840' PB.**

Pull producing equipment from both zones. Run Baker Model "D" latching type packer plug and latch into Model D packer at 5635'. Run bailer on sand line and dump 10 to 15' of 8-12 frac sand on top of packer. Dump 2 sacks of cement on top of sand. Run 2-3/8" tubing and set at approximately 5175'. Run rods and pump and return South Paddock zone to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY SIGNED <b>C. D. BORLAND</b>	TITLE <b>Area Production Manager</b>	DATE <b>June 10, 1969</b>
APPROVED BY <b>John W. Runyan</b>	TITLE	DATE <b>JUN 12 1969</b>
CONDITIONS OF APPROVAL, IF ANY:		