

EXXON COMPANY, U.S.A.

POST OFFICE BOX 1600 • MIDLAND, TEXAS 79702-1600

MIDLAND PRODUCTION ORGANIZATION

OPERATIONS INTEGRITY

May 2, 1995

New Mexico -S- State #25L
N-02-22S-37E, Lea County
(Follow-up to phone call on
Friday, April 28, 1995)

New Mexico Oil Conservation Division
District I
P.O. Box 1980
Hobbs, New Mexico 88240

Attention: Mr. Jerry Sexton
District I Supervisor

The following is an updated history:

Tubingless triple completion; all three 2 7/8" tubing strings cemented to surface:

String #1 (North)	3-19-91	Drinkard perfs (6255' - 6486') were abandoned with CIBP at 6200' with 20' cement dumped on top.
	3-22-91	Blinebry Oil and Gas Pool perforated (5672' - 5814').
	*4-11-91	Blinebry Oil and Gas Pool reperf'd (5680' - 5720').
String #2 (Southeast)	2-21-76	Wantz Abo perf'd (6639' - 6897').
	5-15-91	Wantz Abo reperf'd (6520' - 7155').
	7-16-91	RBP set at 6000', no cement dumped on top.
	7-24-91	While swabbing, lost 10' wireline above rope socket and swabbing tools. Still in String #2.
String #3 (Southwest)	12-5-91	Cemented Grayburg perfs (3678' - 3746') and tubing string to surface. Zone abandoned.

After completing extensive well file research and verification of same with reservoir engineer, Exxon would like to amend the Form C-105 filed 9/21/94, which inadvertently reflected that Wantz Abo pool (String #2) was abandoned with a CIBP at 6000'.