Submit 3 Copies to Appropriate District Office	State of New Mex Energy, Minerals and Natural Res	Form C-103 Revised 1-1-8	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATIO P.O. Box 2088	WELL API NO.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410	6. State Oil & Gas Lease No.		
(DO NOT USE THIS FORM FOR PRO DIFFERENT RESENT	ICES AND REPORTS ON WELL DPOSALS TO DRILL OR TO DEEPEN (RVOIR. USE "APPLICATION FOR PER -101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL	OTHER		Sunshine Royalty
2. Name of Operator		······································	8. Well No.
Mewbourne	Oil Company		9. Pool name or Wildcat
3. Address of Operator	270 Hobbs, New Mexico	88241	South Brunson Drinkard-Abo
4. Well Location			
Unit Letter <u>E</u> : <u>198</u>	0 Feet From The North	Line and66	50 Feet From The West Line
Section 17	Township 22S Rar 7////// 10. Elevation (Show whether I		NMPM Lea County
	Appropriate Box to Indicate N	Nature of Notice, R	eport, or Other Data
NOTICE OF IN	TENTION TO:	SUB	
		REMEDIAL WORK	
	CHANGE PLANS		GOPNS. 🔲 PLUG AND ABANDONMENT 💹
PULL OR ALTER CASING		CASING TEST AND CI	
OTHER:		OTHER:	
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	ztions (Clearly state all pertinent details, an	d give pertinent dates, inclu	iding estimated date of starting any proposed
04/10/92 Move on and rig up E TAC. POOH with 2 3/	unice Well Service 15. 8" tubing and 7" TAC. (Unseat pump, P Close well in a	OOH with rods and pump. Unseat nd build fence around pit.
with tubing. Tag CI CIBP. Pull to 5782' cement. Pull to 278	BP. Circulate hole and . Spot 100 sacks of C of 21 Spot 25 sacks of C	mix mud. Spot cement. Pull t cement. POOH. 208'. Establis	/Gas Commission witness. RIH 20 sacks of cement on top of o 3300'. Spot 25 sacks of C Perforate with 5 shots at h rate and got circulation on packer and POOH.
04/14/92 RIH with tubing and	tag plug at 1201'. POOD stall dry hole marker.	H. Call oil an RD and move of	d gas Comm. Talked to Bonnie.
<u>Set surface piug, in</u> I hereby certify that the information above is t	nue and complete to the best of my knowledge and	belief.	
SKONATURE			Sup t DATE05/08/92
TYPE OR PRINT NAME Bill Pi	erce		TELEPHONE NO. 393-5905
(This space for State Use)			S INSPECTOR NOV 0 9 '92
APPROVED BY Charling	errin m		DATE

1	1	1
2	٤l	<u>م</u>

-

-

-

Hobbs P.O. Box 1980 Hobbs, NM 88240	Artesia P.O. Drawer DD Artesia, NM 88210	Aztec 1000 Rio Brazos Aztec, NM 87410
NOTICE OF GAS WEL	L - CONNECTION / RECONNE	CTION / DISCONNECTION
This is to notify th	e Oil Conservation Division	n of the following:
Connection	_ First Delivery Dat	e Initial Potential
Reconnection	_ First Delivery Dat	e Initial Potential
Disconnection X	_	
for delivery of gas	from the <u>Mewbourne Oil</u> Oper Sunshine Roya	ator
161000198 Meter Code Site Co	Lea <u>1</u> <u>Vell No.</u> Unit Le	.se
was made on4/22/9 date	2 >	
AOF	Warren Petr	oleum Company
Choke		isporter
OCD use only County Land Type Liq. Transporter		tive Name/Title type or print)

Submit in duplicate to the appropriate district office.

.

.

Sabmit 3 Copies lo Appropriate District Office		of New Mexico Natural Resources Department	F(7., C43 Revised 1-1-8
DISTRICT I P.O. Box 1950, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088 Device 87504 2088			WELL API NO.
			5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 874	410		6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR DIFFERENT R (FOI	NOTICES AND REPORTS PROPOSALS TO DRILL OR T ESERVOIR. USE "APPLICATIK RM C-101) FOR SUCH PROPO	O DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
. Type of Well: OIL GAS WELL X WELL	OTHER		Sunshine Royalty Co.
Name of Operator			8. Well No.
Mewbourne Oil Comp	any		# 1
Address of Operator	· .		9. Pool name or Wildcat
P. 0. Box 5270	Hobbs, New Mexico	88241	South Brunson Drinkard -Abo
J. Well Location	1980 Feet From The Nor	th Line and 660	D Feet From The Line
	0.00		NMPM Lea County
Section 17	Township 22S	Range 38E. Show whether DF, RKB, RT, GR, etc.)	
		3314 GR	
	eck Appropriate Box to	Indicate Nature of Notice,	Report, or Other Data
	INTENTION TO:	SU	BSEQUENT REPORT OF
ſ			
ERFORM REMEDIAL WORK	PLUG AND ABANE		
EMPORARILY ABANDON	CHANGE PLANS		
ULL OR ALTER CASING		CASING TEST AND	
DTHER:			
work) SEE RULE 1103.			cluding estimated date of starting any proposed
1.) Set CIBP @	6950' and cap w/35'	of cement.	
2.) Load hole w	ith plug mud.		
3.) Spot cement	plug from 5782' -	5350' across perforat	lons.
4.) Spot 100' c	ement plug at 3300	at top of Queen form at top of Yates form	ation.
5.) Spot 100' c	ement plug at 2700	and tag plug	ERF & SQUEEZE
6.) Spot 100' c	ement plug from 100) to surface.	·····
7.) Spot 100' c	hole marker and c	lean location.	
8.) Install dry	note marker and a		
I hereby certify that the information abo	we is true and complete to the best of m	y knowledge and belief.	
SKONATURE	Fience	mre Production	Superintendent DATE March 10, 199
i Rill	Pierce		TELEPHONE NO. 393-590
TYPE OR PRINT NAME	Orig. Signed by		
(This space for State Use)	Paul Kautz		
· ·	Geologist		MAR 2
APPROVED BY		TILE	DATE
CONDITIONS OF APPROVAL, IF ANY:		AUGT IT NOTERO 24	
		n merina and one	
		TIONS FOR THE CIUS	