

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. BOX 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-20562

5. Indicate Type of Lease

☐ STATE

☒ FEE

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

GRIZZELL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

☒ OIL WELL

☐ GAS WELL

☐ OTHER

2. Name of Operator

APACHE CORPORATION

3. Address of Operator

2000 POST OAK BLVD., SUITE 100, HOUSTON, TX 77056-4400

8. Well No.

9

9. Pool name or Wildcat

BLINEBRY OIL & GAS (OIL)

4. Well Location

Unit Letter O : 810' Feet From The South Line and 1980' Feet From The East Line
Section 8 Township 22S Range 37E NMPM Lea County

10. Elevation (Show whether DF, RKB, RI, GR, etc.)

3412' DF

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

☐ Perform Remedial Work

☐ Plug and Abandon

☐ Temporarily Abandon

☐ Change Plans

☐ Pull or Alter Casing

☐ Other

☐ Remedial Work

☐ Altering Casing

☐ Commence Drilling Operations

☐ Plug and Abandonment

☐ Casing Test and Cement Job

☒ Other

FRAC BLINEBRY ✓

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

9-1 TO 9-3-98

MIRU SU. POH W/PRODN EQMT. RIH W/PKR SET @2476'. TEST PLUG @5400' TO 3000#. TEST PLUG @6009' TO 3000#. REL PKR & SET @5400'. SPOT W/600 GALS 20% XYLENE HCL. FLUSH W/21 BBLS 1% KCL. PREP TO FRAC. RU FRACMASTER. PUMP 1000 GALS 10% TOLUENE 15% HCL, FOLLOW W/3000 GALS 15% NEFE, 100 BBLS 25# BORATE XL @18 BPM & 4100#. PREP TO REPERF.

9-10 TO 9-14-98

POH W/PKR. PERF BLINEBRY ZONE IN 6 RUNS @5422'-36', 5466'-96', 5534'-38', 5572'-80', 5608'-10', 5650'-58', 5708'-12', 5839'-45', 5863'-67', 320 HOLES. RDWL. SPOT W/600 GALS 15% NEFE HCL. ACIDIZE W/6000 GALS 15% BxDx HCL IN 5 STAGES DIVERTED W/7500# RS @9 BPM & 3200#. FLUSH W/65 BBLS 1% KCL. FRAC W/833 BBLS AQUAMASTER 25 W/56000# 16/30 CR4000. SCREEN OUT. RD. REL PKR & POH.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Frances M. Byers

TITLE

SR. ENG. TECH

DATE 9-11-98

TYPE OR PRINT NAME

FRANCES M. BYERS

TELEPHONE NO. (713)296-6000

(This space for State Use)

ORIGINAL SIGNED BY

APPROVED BY

DAVE WINK

TITLE

DATE 10-1-98

CONDITIONS OF APPROVAL, IF ANY

FOR REVIEW