Form 3160-5 (June 1990)

UNITED STATES

N.M. Oil ons. Division 1625 N. French Dr. Hobbs NM 88240

FORM APPROVED

	LAND MANAGEMENT	Expires: March 31, 1993
		5. Lease Designation and Serial No. LC032104
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		
Use "APPLICATION FO	ill or to deepen or reentry to a different reservoir. DR PERMIT-" for such proposals	, was a second of the second o
		7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE 1. Type of Well		7. II Only of CA, Agreement Designation
Oil Gas		
Well		8. Well Name and No.
Texaco E & P Inc.		A.H.Blinebry Fed NCT 4-4
3. Address and Telephone No.		9. API Well No.
P.O.Box 3109 Midland, Texas 79702 (915) 688-4492		30-025-20921 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit M, 990 FSL, 990 FWL, Sec 31-22S-38E		Brunson Drinkard
		11. County or Parish, State
	•	Lea County, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, O	R OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
☐ Notice of Intent	Abandonment	Change of Plans
Pa	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
Final Abandonment Notice	Casing Repair	Water Shut-Off
	Altering Casing	Conversion to Injection
	Other	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly st	ate all pertinet details, and give pertinent dates, including estimated date o	
7-20-98Inform BLM of intent to plug well, MII	are all pertiner details, and give perfinent dates, including estimated date of ured and true vertical depths for all markders and zones perfinent to this w	ork.)*
7-21-90POOM W/half of tubing wireline not a	available	
/-22-98Set 2 //8" CIBP @ 6530' Y strings	Set 2.7/8" CIRD @ 54201 V -+	
- 1 20 00 INII WILDU, IAU LIDP (II) DA HI X EFFIN	O Would not sire. Jete	
		@5200 in X string
RIH tag cement @ 5600' snot 15 sy o	g, Spot 3 sx on top, thix salt gel and pump, Spot 15 sx cem	ent @ 5630' Y string WOC 4 hrs
7-28-98RIH, tag no cement, BLM okaved to	set CIBP @ 5200' Vistring tog CIBB @ 52001: Visit	nd
and RIH of X string and tag CIBP @ 52	200' and spot 10 sx cement, POOH	nd spot 10 sx cement, POOH
- 1-49-90-1011 A SUBD. (ad cement (a) 5007' Da	OOH DILL Victoria and description of a second and a second a second and a second and a second and a second and a second an	and RIH set down @ 2600'
7-31-98RIH to tag cement no tag POOH R	f string, spot 10 sx cement, WOC 4 hrs, RIH tagged no centre where the 2000# and ROOM is the string.	nent, spot 15 sx cement SION
@ 2650'	"Transpacker, pressure test to 5000#, good, POOH, okayed	by BLM to spot 20 sx cement
8-03-98RIH tag cement @ 880', RIH X string	to 2650' spot 15 sx cement, cut X string @ 1289', casing r	of free numn 50 average
cut @ 1289', displace to 1050', WOC	1000 For	to thee, puttip 50 sx cement into
and pump 100 sx cement to surface in 8-05-98RDMO	to 1000 PSI, good, tag cement @ 1040', cut X & Y strings 8 5/8" casing	@ 250', Lay down 2 7/8", Mix
		St of the wed only
	the state of the s	20010
14. I hereby certify that the foregoing is true and correct	Cui va 104 o 12: 10 & 1	Marie see
Signed Aus Light	Title Manager, P&A, Dawson Production Services	00/07/05
(This space for Federal Bat SCIPuse) ES BABY	A):	Date08/07/98
Approved by	Tille Tille	Date 29 2001
Condit ons of approval, if any:	- The state of the	_ Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



ブ