

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instruction  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals.)

|   |  |   |  |
|---|--|---|--|
| 1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>  |  | 7. UNIT AGREEMENT NAME<br>NONE  |  |
| 2. NAME OF OPERATOR<br>TEXACO Inc.  |  | 8. FARM OR LEASE NAME<br>A. H. Blinebry NCT-4                               |  |
| 3. ADDRESS OF OPERATOR<br>P. O. Box 728 - Hobbs, New Mexico   |  | 9. WELL NO.<br>4  |  |
| 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*<br>See also space 17 below.)<br>At surface<br>Well located Unit Letter M, Section 31, 990' from the South Line, and 990' from the West Line, Section 31, T-22-S, R-38-E, Lea County, New Mexico. |  | 10. FIELD AND POOL, OR WILDCAT<br>Blinebry                                  |  |
| 14. PERMIT NO.<br>Regular   |  | 15. ELEVATIONS (Show whether DF, RT, GR, etc.)<br>3324' (D. F.)             |  |
|   |  | 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA<br>Sec. 31, T-22-S, R-38-E |  |
|   |  | 12. COUNTY OR PARISH<br>Lea   |  |
|   |  | 13. STATE<br>N. M.  |  |

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

The following work has been completed on subject well:

1. Pull the pump equipment, and set retrievable bridge plug at 5630'.
2. Perforate the Blinebry String with two jet shots at 5510', 5533', 5544', and 5566'.
3. Acidize perforations with 1200 gallons 24% acid in 3 stages with 30 gallons non-emulsion agent, and 4 ball sealers between stages. Frac perforations with 10,000 gallons gelled brine water with 10,000 pounds sand. Swab well, recover load, and test.
4. On 24 Hour Potential Test well flowed 28 BBL Oil & 12 BBL Water, ending 4:00 P. M. April 15, 1967. GOR - 21,857, GRAVITY - 38.2.

18. I hereby certify that the foregoing is true and correct

SIGNED

*W. E. Morgan*  
W. E. Morgan

TITLE Assistant District Supt.

DATE

April 18, 1967

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side