

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions reverse side)

COPY TO O. C. C.

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

M-1C-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NONE

7. UNIT AGREEMENT NAME

NONE

8. FARM OR LEASE NAME

A. H. Blinebry NCT-1

9. WELL NO.

19

10. FIELD AND POOL, OR WILDCAT  
Blinebry &  
Drinkard11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 29, T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

NOV 19 1964

U. S. GEOLOGICAL SURVEY

HOBBS, NEW MEXICO

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

TEXACO Inc.

3. ADDRESS OF OPERATOR

P. O. Box 728 - Hobbs, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surfaceWell located 660' from the North Line, and 660' from the West  
Line of Section 29, T-22-S, R-38-E, Lea County, New Mexico.

14. PERMIT NO.

Regular

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

3401' (D. F.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Change Casing Plans

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

We propose to make the following plans in the 2 7/8" O. D. Casing program:

Drill to a total depth of 7000'. Run two strings of 2 7/8" O. D. Casing, Blinebry  
Zone, Drinkard Zone. (Hole size 7 7/8"). Cement both strings at 7000'.Cement both strings of 2 7/8" O. D. Casing with 400 Sx. Class "C" 8% gel containing  
friction reducer, plus 400 Sx. Class "C" 4% gel. Test strings of 2 7/8" O. D. Casing  
for 30 minutes with 1500 P. S. I.

18. I hereby certify that the foregoing is true and correct

SIGNED

H. D. Raymond

TITLE Assistant District  
Superintendent

DATE November 18, 1964.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

\*See Instructions on Reverse Side

APPROVED  
NOV 19 1964  
A. R. BROWN  
DISTRICT ENGINEER