

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

N.M. Cons. Division
P.O. Box 1980
Hobbs, NM 88241

FORM APPROVED
Budget Bureau No. 1004-0115
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco E&P Inc.

3. Address and Telephone No.

P.O. Box 3109 Midland, Texas 79702 (915) 688-4492

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980 FNL 660 FWL Sec 20 T22S R38E Unit Letter E

5. Lease Designation and Serial No.

41655

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

A.H. Blinebry Fed NCT-1#

9. API Well No.

30-025-20926

10. Field and Pool, or Exploratory Area

Brunson Drinkard

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Notify BLM of intent to plug
2. MIRU on Z string NU BOP
3. Set 2 7/8" CIBP@ 6860 w/20' cement
4. 10 sx cement 6120-6020
5. 10 sx cement 5600-5500
6. 10 sx cement 5200-5100
7. POH NU on Y string NU BOP
8. Set 2 7/8" CIBP@ 6120 w/20' cement
9. RIH circulate hole w/9.8# mud
10. 10 sx cement 5600-5500
11. 10 sx cement 5200-5100
12. POH NU on X string NUBOP
13. Set CIBP@ 5550' w/20' cement
14. RIH circulate hole w/9.8# mud
15. 10 sx cement 5200-5100
16. Cut and pull 2 7/8" casing (X,Y,Z strings) 3600'±
17. 30 sx cement 3600-3500 WOC/tag
18. 30 sx cement 2630-2530 WOC/tag (Yates)
19. 50 sx cement 1430-1280 WOC/tag
20. 30 sx cement 1280-1160
21. 10 sx cement 30' to surface
22. RDMO, cut off well head, install dry hole marker, clean location

X-Blinebry
Y-Tubb
Z-Drinkard/Abo

RECEIVED
1998 MAY -4 P 2:48
BUREAU OF LAND MGMT.
HOBBS, NEW MEXICO

Signed [Signature] Title Reservoir Engineer

Date 4/28/98

(This space for Federal or State office use)

Approved by (CPIC, SGD.) GARY GOURL

Title ENGINEER

Date MAY 14 1998

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statement or representations as to any matter within its jurisdiction

*See Instruction on Reverse Side