

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐
2. NAME OF OPERATOR
TEXACO Inc.
3. ADDRESS OF OPERATOR
P. O. Box 728, Hobbs, New Mexico 88240
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FWL & 1980' FNL
AT TOP PROD. INTERVAL: (Unit Letter 'E')
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>

(other) To: Downhole Commingle

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rig up. Pull rods & pump in Blinebry string.
2. Clean out Drinkard to 7212'. Set RBP @ approx. 6885'.
3. Perforate Drinkard string w/4 JSPF from 5810-5811'.
4. Set CIBP in Glorieta above perfs. Abandon Glorieta zone. Hold string for future use.
5. Install pumping equipment. Test and place on production as Downhole Commingle of Blinebry and Drinkard formations. NMOCD Administrative Order No. DHC-318, copy attached.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED George H. Stewart TITLE Asst. Dist. Supt. DATE 9-11-80

(Orig. Sgd.) GEORGE H. STEWART (This space for Federal or State office use)

APPROVED BY _____ TITLE ACTING DISTRICT ENGINEER

CONDITIONS OF APPROVAL, IF ANY:

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

5. LEASE LC-032104	
6. IF INDIAN, ALLOTTEE OR TRIBE NAME -	
7. UNIT AGREEMENT NAME -	
8. FARM OR LEASE NAME A.H. Blinebry Fed. NCT-1	
9. WELL NO. 20	
10. FIELD OR WILDCAT NAME Blinebry Oil & Gas and Drinkard	
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 20, T-22-S, R-38-E	
12. COUNTY OR PARISH Lea	13. STATE New Mexico
14. API NO.	
15. ELEVATIONS (SHOW DF, KDB, AND WD) 3398' (DF)	

RECEIVED

SEP 18 1980

SEP 12 1980

S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO