

UNITED STATES OF AMERICA
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

660' FSL & 1980' FWL
AT SURFACE: (Unit Letter 'N')
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐

(other) Of: Abandon San Andres &

Recomplete Blinebry - DHC Blinebry & Drinkard

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Rigged up. Kill San Andre & Drinkard Zones. Install BOP.
2. Set RBP @ 5437' & dump 1 sx. Sand on plug in Drinkard Zone.
3. Squeeze San Andres perfs. 4353'-4467' w/50 sx. Class 'H' Cement containing 2% CaCl. San Andres P & A, 7-14-82.
4. Set RBP @ 4203' in Drinkard String.
5. DOC 4047' - 7059' in former San Andres String.
6. Perf. 2-7/8" Csg. (Former San Andres String) w/2-JSPF in Blinebry

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Asst. Dist Mgr DATE 8-20-82

ACCEPTED FOR RECORD

PETER W. CHESTER

APPROVED BY _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See instructions on Reverse Side

5. LEASE

LC-032104

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

A.H. Blinebry Fed. NCT-1

9. WELL NO.

21

10. FIELD OR WILDCAT NAME

Blinebry, Drinkard & Brunson SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 20, T-22-S, R-38-E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3400' (DF)

NMOCD Administrative Order No.
DHC-340

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED
821021

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local procedures and practices, either are shown below or will be issued by the agency.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

above plugs; amount, size, method of parting of any casing, liner or tubing; and any other data that may be required for final inspection looking to approval of the abandonment.

GPO • 1976 O - 214-149

SECRET
POLITICAL MAT TO THE PRESIDENT
THE WHITE HOUSE

JULY 20 1973 AIR FORCE OFFICE

01888 N.Y. add
10891 S 137 1000
(17) rettel dir

THE TWO DEE THEOLOGICAL

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED
DATE 08-19-2001 BY SP-6
JTB/STP

RECORDED
INDEXED
JAN 10 1964
FBI - NEW YORK

1. Set 207 & 4803, in Building 207, 1000
2. 207 & 4803, in Building 207, 1000
3. 207 & 4803, in Building 207, 1000
4. 207 & 4803, in Building 207, 1000
5. 207 & 4803, in Building 207, 1000
6. 207 & 4803, in Building 207, 1000
7. 207 & 4803, in Building 207, 1000
8. 207 & 4803, in Building 207, 1000
9. 207 & 4803, in Building 207, 1000
10. 207 & 4803, in Building 207, 1000

10-10-68

10-10-68

AUG 30 1982
FBI
HONOLULU OFFICE

17. Describe proposed or completed operations continued:
6. Zone @ 5701', 15', 22', 34', 49', 56', 69', 86', 99', & 5824', & Commingle perfs. from 7060' - 7065'.
 7. Set RBP in Blinebry @ 6700'.
 8. Release & pull RBP in Drinkard Zone @ 4203'. Clean Out. Set pkr. @ 6900'.
 9. Acidize perfs. 6977' - 7069' w/3000 gals. 20% NEFE Acid in 2- Stages using 500# rock salt between stages. Flushed w/21½ Bbls. 2% KCI Water. Pull RBP & packer.
 10. Set pkr. in Blinebry @ 5630'. Communicated Blinebry & Drinkard Zone.
 11. Install pumping equipment. On 24 Hr potential test ending 8-16-82, Well pumped 9 Bbls. Oil & 22 BW. Well Completed as Blinebry-Drinkard Downhole Commingle.

RECEIVED

AUG 30 1982

S.C.D.
HOBBS OFFICE