				1	
Form 9-331 (May 1963)	050107	UN ED STATES	(Osb ! ***		Burcau No. 42-R1424.
		MEN. OF THE INTE	RIOR verse side)		TION AND SERIAL NO.
		GEOLOGICAL SURVEY		LC-032104	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)					OTTEE OR TRIBE NAME
	NONE				
1. 616 5F GAS				7. UNIT AGREEMEN	T NAME
WELL WEI	NOME	<u> </u>			
Z. NAME OF OPERATO	TEXACC]	8. FARM OR LEADE NAME		
3. ADDRESS OF OPERA		A. H. Bline	ebry NUT-1		
	P. O.	9. WELL NO.			
4. LOCATION OF WELL See also space 17	(Report location below.)	10, FIELD AND POO	d, OR WILDCAT		
At surface		Tubb & Drinkard			
Well locate	11. SEC., T., R., M., SURVEY OR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA			
	or Section	28, T-22-S, R-38-E,	, Lea County, N. M.	Sec. 28, T.	-22-S, R-38-E
14. PERMIT NO.		15. ELEVATIONS (Show whethe	r DF, RT, GR, etc.)	12. COUNTY OR PA	RISH 13. STATE
Regular	• • • • • • • • • • • • • • • • • • • •	3373' (D. F.)		Lea	N.M.
16.	Check A	ppropriate Box To Indicate	Nature of Notice, Report, o	r Other Data	
	NOTICE OF INTE			SEQUENT REPORT OF:	* * * * * * * * * * * * * * * * * * *
TEST WATER SHU	T-OFF	PULL OR ALTER CASING		▼	
FRACTURE TREAT		MULTIPLE COMPLETE	WATER SHUT-OFF	REPAIRI.	NG WILL
SHOOT OR ACIDIZE	,	ABANDON*	FRACTURE TREATMENT SHOOTING OR ACIDIZING		G CASING
REPAIR WELL		CHANGE PLANS	(Other)	ABANDON	MENT*
(Other)	<u> </u>		(Note: Report resu	ilts of multiple complet	lon on Well
17. DESCRIBE PROPOSEI proposed work, nent to this worl	OR COMPLETED OP If well is directi	ERATIONS (Clearly state all pertionally drilled, give subsurface l	ment details, and give pertinent darocations and measured and true ver	mpletion Report and Log tes, including estimated tical depths for all mar	
minn cor		10			
TOBB ZONI	5: Ran 723	31 of 2 7/8" 0. D.	Casing, 6.50 LB, J-55	, NEW, and	
cemented	at 72451,	ring at 66121.			

DRINKARD MONE: Ran 7236 of 2 7/8" 0. D. Casing, 6.50 LB, J-55, NEW, and cemented at 7248, Plug at 7242.

Cemented above strings of 2 7/8" 0. D. Casing with 400 Sx. Incor 8% gel with FRA, 200 Sx. Incor 8% gel, plus 400 Sx. Incor 4% gel. Pump each plug down with 500 gals acetic acid. Tested above strings of 2 7/8" 0. D. Casing for 30 minutes with 1500 P. S. I. from 8:00 A. M. to 8:30 A. M. May 12, 1965. Tested 0. K. Job complete 8:30 A. M. May 12, 1965.

S. I hereby certify that the foregoing is true and correct			
SIGNED H. D. Raydocc) Assistant District Superintendent	DATE .	May 13, 1965
(This space for Federal or State office use)	Dupta Invendente		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE _	
, == ====		APPROVE	כ ל"

*See Instructions on Reverse Side

MAY 1 5 1965