(June 1990)

N.M. Ol' ons. Division 1625 N. French Dr. FORM APPROVED
Hobbs, NM 88240 Expires: March 31, 1993 5. Lease Designation and Serial No. L.C. 032104 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation 8. Well Name and NoA . H . Blinebr Fed NCT 1 #31 9. API Well No. 30-025-21409 10. Field and Pool, or Exploratory Area O. Field and Pool, or English Brunson Drinkard ABO -11. County or Parish, State Lea, New Mexico TYPE OF ACTION Change of Plans **New Construction** Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) Approved as to plugging of the well bare. Liability under bond is retained until surface restoration is completed.

UNITED STATES Form 3160-5 DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE i. Type of Well X Oil Well Gas Well 2. Name of Operator Texaco Exploration & Production, Inc. 3. Address and Telephone No. P. O. Box 3109, Midland, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter F, 1980' FNL, 1650' FWL Section 28, Township 22S, Range 38E CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION Abandonment Notice of Intent Recompletion Plugging Back Subsequent Report Casing Repair Final Abandonment Notice Altering Casing 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* Tag TOC Z-Side (Tubb) @ 6400' Fill 2 7/8" Csg w/120 Sx Cmt 6400'-1500' Set 2 7/8" CIBP @ 7050' Y-Side (Drinkard ABO) Fill 2 7/8" Csq w/75 2. Sx Cmt 7050'-4200' 3. Perf 6 hoes Y-Side @ 3727' & 3581'. Unable to Sqz Perfs pressure test Perfs w/2300 PSI no leaks for 20 minutes, spot 12 Sx Cmt 3777'-3350' Perf 6 holes Y-Side @ 2834' Sqz Perfs w/70 Sx Cmt 2834-2500' (B-Salt, Yate 4. Tag Cmt @ 1827' Cut 2 7/8" Csg @ 1500' Z-Side unable to get down on Y-Side, Cut 2 7/8" 5. Csg @ 432', Spot 75 Sx Cmt 1567-1300', Tag no Cmt, Re-spot 75 Sx Cmt 1567'-1300', Tag Cmt @ 1450'. Re-spot 45 Sx Cmt 1450'-1300'. Tag Cmt @ 1280' (8 5/8" shoe, T-Salt) Displace hole w/salt gel mud 9.5# Brine w/25# gel P/BBL 6. Spot 15 Sx Cmt 61' to surface, Install dry hole marker. 7. 14. I hereby certify that the foregoing is true and correct Tide VICE- TRESIDEN (This space for Federal or State office use PETROLEUM ENGINEER MAR 0 9 2001 Approved by ORIG SGD.) I ES BABYAK Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

