

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
TEXACO Inc.
Address of Operator
P. O. Box 728, Hobbs, New Mexico 88240

7. Unit Agreement Name

8. Farm or Lease Name
W. L. Nix

9. Well No.
5

Location of Well
UNIT LETTER G 1980 FEET FROM THE East LINE AND 1980 FEET FROM
North 20 TOWNSHIP 22-S RANGE 38-E NMPM.

10. Field and Pool, or Wildcat
Drinkard

15. Elevation (Show whether DF, RT, CR, etc.)
3401' (DF)

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
REPAIR OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ATTEMPT CASING REPAIR - P & A ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. RIGGED UP. INSTALL BOP.
2. CUT 2 7/8" @ 2985' AND PULL SAME.
3. SET RBP @ 62'. REPAIR CASING @ WELLHEAD. PULL RBP.
4. FISH RODS. COULD NOT RECOVER ALL JUNK IN HOLE.
5. SET CIBP @ 6518' AND SPOT 35 SX CEMENT ON TOP OF PLUG FROM 6518-5330'.
6. SPOT 15 SX CEMENT PLUG FROM 4812-4100'.
7. PUMP 110 SX CEMENT @ CASING CUT OFF POINT OF 2985'. TOP OF CEMENT @ 2805'.
8. SPOT 115 SX CEMENT PLUG FROM 2805-2712'.
9. SPOT 100 SX CEMENT PLUG FROM 2712-2630'.
10. SPOT 75 SX CEMENT PLUG FROM 2598-1400'.
11. SPOT 100 SX CEMENT PLUG FROM 1400-1200'.
12. SPOT 10 SX CEMENT PLUG FROM 62'-SURFACE.
13. INSTALL DRY HOLE MARKER. CLEAN LOCATION. PLUG AND ABANDON, 12-4-84.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TO R. Frank Gray

TITLE District Operation Mgr

DATE 12-7-84

APPROVED BY R. A. Sudler

TITLE OIL & GAS INSPECTOR

DATE 4-26-85

CONDITIONS OF APPROVAL, IF ANY: