API DU URD-	X + 4 4 4		se sa
Form 9-331 (May 1963) DEPA	UNE DISTATES RTMENT OF THE INTE	SUBMIT IN TRIPL 24 (Other instructions 2 RIOR verse side)	
	GEOLOGICAL SURVEY		New Mexico 0356435
	OTICES AND REPORTS roposals to drill or to deepen or plu PLICATION FOR PERMIT for such		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS OTHE	2R		7. UNIT AGREEMENT NAME
2. NAME OF OFERATOR			8. FARM OR LEASE NAME
Union Oil Company of California 3. ADDRESS OF OPERATOR			Federal "L"
	ply Co., Box 2010, Ho ion clearly and in accordance with a	bbs, N. M. 88240 ny State requirements.*	# 1 10. FIELD AND POOL, OR WILDCAT
330' FSL & 330' FEL			11. SEC., T., R., M., OR BLK. AND SURVEY OR ABEA 34-235-32E
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	3609' GR		Lea N. M.
TEST WATER SHUT-OFF FRACTORE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other) 17. DESCRIBE PROPOSED OR COMPLETE	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS D OPERATIONS (Clearly state al. pertin	Completion or Recomposition of Recomposi	REPAIRING WELL
1. Spotted a 25 2. Loaded hole w 3. Pulled casing 4. Spotted a 35 5. Spotted a 50 6. Spotted a 10	sx plug to cover all p ith mud-laden fluids. from approximately l sx plug @ casing stub sx plug @ 830'.	perforations. ,650'. t a 4" regulation marke	

18. I hereby certify that the foregoing is true and correct		
SIGNED Stanley Miken	TITLE	Agent 5/30/73
(This space for Federal or State office use)		AP 1973 2015
APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITEE	ANIMUR R. BADWINDATE
*S	ee Instruction	ns on Revence Side