

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG LACK TO A DIFFERENT RESERVOIR.
SEE APPLICATION FOR PERMIT AND (FORM) C-101 FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER-

2. Name of Operator
Southland Royalty Company

3. Address of Operator
21 Desta Drive, Midland, Texas 79701

4. Location of Well
UNIT LETTER P 990 FEET FROM THE South LINE AND 660 FEET FROM
THE East LINE, SECTION 36 TOWNSHIP 22S RANGE 37E NMPL.

5a. Indicate Type of Lease
State ☒ Fee ☐

5. State Oil & Gas Lease No.
E-6143

7. Unit Agreement Name

8. Form of Lease Name
State BD "36"

9. Well No.
2

10. Field and Pool, or Wildcat
Blinebry

12. County
Lea

15. Elevation (Show whether DF, RT, CR, etc.)
3304' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Obtain oil & wtr samples.
2. MIRUPU. POH w/rods. Instl BOP. POH w/tbg.
3. RIH w/bit on DC's. Drl out sulfate scale. POH w/bit.
4. RIH w/4 3/4" smooth tooth Kutright shoe on wash pipe. Wash over tbg to pkr. POH.
5. RIH w/overshot, bumper sub, jars & DC's. Jar pkr & tbg tailpipe loose. POH w/fish.
6. RIH w/bit & scrapers. Clean out & POH w/bit.
7. Reperf Blinebry zone @ 5468-5728'.
8. RIH w/RBP & pkr. Set RBP. Drop spot valve. Spot 100 gals 15% HCl & set pkr. POH w/spot valve. Acdz pfs. Flush to btm pf.
9. Set RBP. Drop spot valve. Spot 140 gals acid. Set pkr. POH w/spot valve. Acdz pfs. Flush to btm pf.
10. POH w/RBP & pkr. RIH w/prod equip & set pmp. Return to pmpg.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED F.N. RAD by D Roberts TITLE District Operations Engineer DATE 7/18/83

ORIGINAL SIGNED BY EDDIE SEAY

APPROVED BY OIL & GAS INSPECTOR TITLE _____ DATE JUL 21 1983

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
JUL 20 1983
O.C.D.
HOBBES OFFICE