. C COPIES HECEIVED		Form C-103	
TRIBUTION		Supersedes Old	
FE.	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65	
FILE		2.100/1140 1-1-002	
U.S.G.S.		5a. Indicate Type of Lease	
LAND OFFICE		State Fee	777
			<u> </u>
OPERATOR		5. State Oil & Gas Lease No.	
		İ	
SUNDR	Y NOTICES AND REPORTS ON WELLS		$TT_i$
(DO NOT USE THIS FORM FOR PRO USE **APPLICATI	Y NOTICES AND REPORTS ON WELLS  POSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT REBERVOIR.  ION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)		///
1.		7. Unit Agreement Name	777
OIL X GAS WELL	OTHER-	The state of the s	
2. Name of Operator	VIII.		
		8. Farm or Lease Name	
Gulf Oil Corporation 3. Address of Operator		Hugh	
o, Address of Operator		9, Well No.	
Box 670, Hobbs, New Me	xico 88240	Q	
4. Location of Well		10. Field and Pool, or Wildcat	
UNIT LETTER E 2	030° FEET FROM THE NOTTH LINE AND 560 FEET PRO	D=4 -1 1	
	FEET FROM THE MOLCIE LINE AND JOU FEET FRO	Prinkard	•
Wast	1/		$^{\prime\prime\prime}$
THE HESE LINE, SECTIO	N 14 TOWNSHIP 22-S RANGE 37-E NMPI	~ (	111:
mmmmmm			$^{\prime\prime\prime}$
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County	771,
			///
Check A	Appropriate Box To Indicate Nature of Notice, Report or O		777
NOTICE OF IN			
1101102 01 111	SUBSEQUEN	NT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	$\overline{\Box}$
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB		
<b>-</b> •	OTHER		
OTHER Perforate addition	onal zone, frac		ш
& acidize.			
<ol> <li>Describe Proposed or Completed Oper work) SEE RULE 1703.</li> </ol>	erations (Clearly state all pertinent details, and give pertinent dates, includin	ig estimated date of starting any propo	sed
2011) TEL NOLE 1103.		, , , , ,	
6519' PB.			
Pull producing e	uninment Deminute aliketaria nee		
2 72" TUDE 62001	quipment. Perforate additional Drinkard zone	in 5-1/2" casing with	
4, •/4 JRFF ME 0209 1	EO DJYZ'. Kun treating equipment. Tweet all.		
0470 and new periorar	LONS With 25.000 gallons of gal bring water and	1 2000 11 6 100	
WE GOTO LTGOIL ATCH T	JA VALIELB OI VAL WATAT. Pull trooting aguilan.		
2-3/8" tubing and set p	packer at approximately 6225'. Swab and clean	enes and maker off	
production.	arparentary outs a swap and clean	ab and Letatu Mett Co	
-			
	·		
18. I hereby certify that the information a	bove is true and complete to the best of my knowledge and beilef.		
	and and complete to the obst of my knowledge and belief.		
D/1 /10/-			
SIGNED //. V. Willa	seale TITLE Area Engineer	DATE November 29, 19	72
		THE REFERENCE AS 19	<u> </u>
$\mathcal{O}$			
//			

CONDITIONS OF APPROVAL, IF ANY