NO. OF COPIES RECEIVED	]	Form C-103
DISTRIBUTION		Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE		
U.S.G.S.	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	5a. Indicate Type of Lease
LAND OFFICE	nou v	State X Fee
OPERATOR	]	5, State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PR	RY NOTICES AND REPORTS ON WELLS  OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  FION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL A GAS WELL GAS	OTHER-	7 Langthe Watth: Penrose Sand Unit
2. Name of Operator  Anadarko Production Company		8. Farm or Lease Name Tract 21
3. Address of Operator		9. Well No.
P. O. Box 247, Hobbs, New Mexico		8
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTERC	810 FEET FROM THE North LINE AND 1980 FEET	Langlie Mattix
	24 <b>22 S</b> 37 F	NMPM.
	15. Elevation (Show whether DF, RT, GR, etc.) 3319' GR	12. County
	Appropriate Box To Indicate Nature of Notice, Report on Nation To:	r Other Data JENT REPORT OF:
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	PLUG AND ABANDON REMEDIAL WORK  COMMENCE DRILLING OPNS.  CHANGE PLANS CASING TEST AND CEMENT JQB	ALTERING CASING PLUG AND ABANDONMENT
OTHER		
17. Describe Proposed or Completed O work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates, inc	luding estimated date of starting any proposed
1. Drilled out ceme	ent plug in 10–3/4" surface casing with an 8–3/4" bits with 8–3/4" bit. On TD 7/11/66.	it. Drilled to total
2. Ran 3706' of 7"	OD 20# J-55 used casing with a float shoe.	
3. Comented with 3 800° on casing.	350 sacks regular cement. Plug down at 2:00 PM 7/	11/66. Shut in with
4. After 36 hours p	ressure tested casing to 2000 without pressure loss for	or 30 minutes.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 8/9/66 TITLE Project Supervisor APPROVED BY