

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-3480-1

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation	8. Farm or Lease Name R. E. Cole (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, N.M. 88240	9. Well No. 8
4. Location of Well UNIT LETTER <u>K</u> <u>2130</u> FEET FROM THE <u>south</u> LINE AND <u>2130</u> FEET FROM THE <u>west</u> LINE, SECTION <u>16</u> TOWNSHIP <u>22S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Drinkard
15. Elevation (Show whether DF, RT, GR, etc.) 3392' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>		OTHER <u>Acidized</u> <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6645' PB.

Checked CIBP at 6655' with 1000# 30 minutes, OK. Pulled tubing and packer. Acidized perforations 6454-6567' with 2500 gallons 15% NE acid. Flushed with 15 barrels of oil. 0# pressure. ISIP vacuum. Ran tubing and packer, set packer at 6445'. Swabbed and cleaned up well. Would not flow. Installed pumping equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. B. Boydland</u>	TITLE <u>Area Engineer</u>	DATE <u>7-18-75</u>
Original Signed by <u>John Remyer</u>	TITLE <u>Geologist</u>	
APPROVED BY _____	TITLE _____	DATE <u>JUL 21 1975</u>

CONDITIONS OF APPROVAL, IF ANY: