	AMENDEI	D	Form C-103
NO. OF COPIES RECEIVED			Supersedes Old
DISTRIBUTION			C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	ERVATION COMMISSION	Effective 1-1-65
FILE			5a. Indicate Type of Lease
U.S.G.S.			State XX Fee
LAND OFFICE			5. State Oll & Gas Lease No.
OPERATOR			
		·	E-3480-1
SUNDRY	NOTICES AND REPORTS ON DOSALS TO DRILL OR TO DEEPEN OR PLUG BA	ICK TO A DIFFERENT RESERVOIR.	
1.			7. Unit Agreement Name
	OTHER-		
2. Name of Operator		· · · · · · · · · · · · · · · · · · ·	8. Farm or Lease Name
	R. E. Cole (NCT-A)		
Gulf Oil Corporatio	9. Well No.		
	8		
Box 670, Hobbs, New	0 10. Field and Pool, or Wildcat		
4. Location of Well		0120	
UNIT LETTER K ,]	30 FEET FROM THE South	LINE AND 2130 PEET P	ROM Cary Montoya
	- /	2010	
THE West LINE, SECTION	16 <u>225</u>	87E NA	лөм: <u>(()))))))))))))))))))))))))))))))))))</u>
	15, Elevation (Show whether)	; 	
	12. County		
	339	2' GL	
^{10.} Check A	ppropriate Box To Indicate N	ature of Notice. Report or	Other Data
NOTICE OF IN			ENT REPORT OF:
NOTICE OF IN	TENTION TO:		
	PLUG AND ABANDON		ALTERING CABING
PERFORM REMEDIAL WORK		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON			
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	Cormack Silurian &
OTHER	L	attempted to complet	te in Cary Montoya
	attions (Clearly state all pertinent dets	uls, and give pertinent dates, inclu	ding estimated date of starting any proposed

work) SEE RULE 1103. AMENDED REPORT

7295' PB. 7302' TD.

Pulled producing equipment.Squeezed Silurian perforations 7186' to 7210' with 150 sacks of Class C cement at 3,000# pressure. Cleaned out to 7295'. Perforated 7" casing in Montoya zone with 4, ½" JHPF at 7284-86' & 7255-57'. Ran treating equipment and treated new perforations with 2,000 gallons of 20% NE acid. Pulled treating equipment. Ran 2-3/8" tubing and set at 7270'. Ran rods and pump. Pumped well approximately two weeks with no indication of commercial production.

Plans have been made to abandon Montoya and complete in Drinkard as follows: Pull producing equipment. Set CI BP at 6655' and cap with 10' cement, abandoning Montoya perforations 7255' to 7286'. Perforate Drinkard zone in 7" casing in the approximate interval 6382' to 6567'. Run treating equipment and test BP with 2,000#. Treat new perforations with 2,000 gallons of 15% NE acid and frac with 10,000 gallons of gel brine and 25,000 gallons containing 1 to 2# SPG. Flush with 2,000 gallons of gel water. Pull treating equipment. Run 2-3/8" tubing. Swab and clean up and return well to production.

18. I hereby certify that	the information above is true and cor	nplete to the bes	t of my knowledge and belief.	
SIGNED	Hanbick		Area Engineer	DATE7-8-74
·	An and a second s			
APPROVED BY				DATE

)