

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-22470
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Hugh
2. Name of Operator Anadarko Petroleum Corporation	8. Well No. 10
3. Address of Operator P.O. Box 806 Eunice, NM 88240	9. Pool name or Wildcat Penrose Skelly GB
4. Well Location Unit Letter E : 1650 Feet From The North Line and 330 Feet From The West Line Section 14 Township 22S Range 37E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3376 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. (BP set @ 3000' w/10' sand on BP) TIH w/ 5½" cement retainer to @ 930', pump 100 SX Class C Cement below retainer w/50' cement on top.
2. Circ hole from TOC (880') to surface w/10# brine gel (25#/BL gel).
3. Pull 400' 5½" csg (TOC 400') Spot 10 SX surface plug.
4. Install P & A marker, clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rick L. Langley TITLE Field Foreman DATE 8-20-91
TYPE OR PRINT NAME Rick L. Langley TELEPHONE NO. 394-3184

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NOT BE NOTIFIED 24
HOURS BEFORE THE
CLOSING OF THE
OFFICE FOR THE CLASS