

DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

1a. Indicate Type of Lease	
State ☐	Fee ☒
5. State Oil & Gas Lease No.	
N/A	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒	CAS WELL ☐	OTHER ☐
Name of Operator		
Hanson Operating Company, Inc.		
Address of Operator		
P. O. Box #1515, Roswell, New Mexico 88202-1515		
Location of Well		
UNIT LETTER	N	640
		FEET FROM THE
	South	LINE AND
		1650
		FEET FROM
THE	West	LINE, SECTION
		19
		TOWNSHIP
		22-S
		RANGE
		38-E
		N.M.P.M.

7. Unit Agreement Name
N/A
8. Farm or Lease Name
MAX GUTMAN
9. Well No.
5
10. Field and Pool, or Wildcat
Blinbry
12. County
Lea

15. Elevation (Show whether DF, RT, GR, etc.)
3358' KB

6. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☒
TEMPORARILY ABANDON ☐	COMMENCE DRILLING OPNS. ☐
PULL OR ALTER CASING ☐	CASING TEST AND CEMENT JOB ☐
OTHER ☐	OTHER ☐
PLUG AND ABANDON ☐	ALTERING CASING ☐
CHANGE PLANS ☐	PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perf interval 5489 - 5527' (15 holes).
Set BP @ 5557', set pkr @ 5400'.
Acidized w/3,000 gals NE acid.
Frac w/50,000 gals gel wtr & 95,000# 20/40 sand.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHECKED <u>Brenda K. Godfrey</u>	TITLE <u>Production Analyst</u>	DATE <u>10/25/85</u>
ORIGINAL SIGNED BY JERRY SEXTON		OCT 29 1985
DISTRICT SUPERVISOR		
PROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

OCT 28 1985

C.C.D.
HOBBS OFFICE