

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
ANTA FE	
ILE	
S.G.S.	
AND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPCEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - II" (FORM C-101) FOR SUCH PROPOSALS.

1. ☐ OIL ☐ GAS ☐ WELL ☐ OTHER- TA

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 670 Hobbs, NM 88240

4. Location of Well
D 990 North 330

5. LETTER West 16 22S 37E
6. LINE, SECTION TOWNSHIP RANGE NMPM.

11. Elevation (Show whether DF, RT, GR, etc.)
3393' GL

7. Unit Agreement Name

8. Farm or Lease Name
R.E. Cole (NCT-A)

9. Well No.
12

10. Field and Pool, or WHdest
Drinkard

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

1. REMEDIAL WORK ☐
2. PARTIALLY ABANDON ☐
3. ALTER CASING ☐
4. Repair Casing Leak ☒

5. PLUG AND ABANDON ☐
6. CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

7. REMEDIAL WORK ☐
8. COMMENCE DRILLING OPNS. ☐
9. CASING TEST AND CEMENT JOBS ☐
10. OTHER ☐

11. ALTERING CASING ☐
12. PLUG AND ABANDONMENT ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Find and isolate casing leak. Repair as necessary. Test casing to 500 psi for 30 minutes.
Return well to TA'd status.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Richard A. Sitt

TITLE Division Drilling Manager

DATE 10-14-1986

ORIGINAL SIGNED BY JERRY SEXTON

BY DISTRICT SUPERVISOR

TITLE

DATE

COPIES OF APPROVAL, IF ANY: