

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-22980
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name JONES
2. Name of Operator PIERCE PRODUCTION COMPANY	8. Well No. 3
3. Address of Operator PO BOX 1969, EUNICE, NEW MEXICO 88231	9. Pool name or Wildcat WANTZ ABO
4. Well Location Unit Letter <u>E</u> : <u>660</u> Feet From The <u>WEST</u> Line and <u>1980</u> Feet From The <u>NORTH</u> Line Section <u>6</u> Township <u>22S</u> Range <u>38E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3351 GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-9-91-Remove marker & build cellar
9-10-91-Weld flange on 10-3/4" csgn. Install 6"-900-3500#. Test B.O.P.
9-11-91-Started drilling operations on cement plugs in 10-3/4" csgn & 8-3/4" open hole to top of 7" csgn @ 2800'.
9-23-91-Ran new 7"-23# csgn & Halliburton tool & latched on to the existing 7" csgn. Cemented with 300sx Neat cement.
9-27-91-Drilled out cement & tested csgn to 2000#.Held OK.
9-28-91-Drilled cast iron bridge plug at 5600'.
9-30-91-Squeezed old perfs in csgn-5933'/6107' with 350 sx Neat cement 2% calcium chloride to 4800#.
10-7-91-Drilled out cement & tested perfs to 2000#. Cleaned well out to 7300'.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray A. Pierce TITLE Prod. Supt. DATE 10-28-91
TYPE OR PRINT NAME RAY A. PIERCE TELEPHONE NO. 394-2150

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

OCT 29 1991

000

HOBBS OFFICE