## State of New Mexico

District Office  DISTRICT I		ources Department	Revised 1-1-89
P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO. 30-025-23896
DISTRICT II P.O. Drawer DD, Artesia, NM 88210			5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410			6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELL	LS	
( DO NOT USE THIS FORM FOR PRODIFFERENT RESE	OPOSALS TO DRILL OR TO DEEPEN ( RVOIR. USE "APPLICATION FOR PER 2-101) FOR SUCH PROPOSALS.)	OH PLUG BACK TO A	7. Lease Name or Unit Agreement Name CHRISTMAS
1. Type of Well: OIL GAS WELL X WELL	OTHER		CHRISTMAS
2. Name of Operator	,		8. Well No.
CAMPBELL & HEDRI	CK		9. Pool name or Wildcat
3. Address of Operator  P. O. BOX 401, M.	IDLAND, TEXAS 79702		EUMONT YATES SEVEN RIVERS
A Well Location			O Feet From The EAST Line
Unit Letter O: 330	Feet From The SOUTH	Line and	Feet From The Line
Section 17	Township 22S Ra		NMPM LEA County
	10. Elevation (Show whether I	DF, KKB, KI, GR, etc.)	
(/////////////////////////////////////	Appropriate Box to Indicate ?	Nature of Notice, R	eport, or Other Data
NOTICE OF IN		SUE	SEQUENT REPORT OF
521	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
PENFORM NEWEDINE TOTAL		COMMENCE DRILLING	3 OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS		
PULL OR ALTER CASING	_	CASING TEST AND C	EMENT JOB []
OTHER:		OTHER:	
12. Describe Proposed or Completed Oper work) SEE RULE 1103.	rations (Clearly state all pertinent details, ar	nd give pertinent dates, incli	iding estimated date of starting any proposed
•			
Propose to pul	l rods and tubing, po	erf clean all	perfs and acidize with
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	l rods and tubing, pe E acid with iron con commence on availab	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N	E acid with iron com	ntrol.	
2000 gal 15% N Work over will	E acid with iron con commence on availab	ntrol.	
2000 gal 15% N Work over will	E acid with iron com	ntrol.  pility of wor	ck over rig.
2000 gal 15% N Work over will	E acid with iron con commence on available commence on available completely to the best of my knowledge more	ntrol.	
2000 gal 15% N. Work over will  I hereby certify that the information above is,	Encid with iron concommence on available commence on available completely to the best of my knowledge more	belief.	ck over rig.
2000 gal 15% N. Work over will  I hereby certify that the information above is, SIONATURE	Encid with iron concommence on available commence on available completely to the best of my knowledge more	oility of wor	DATE 8/22/00 TELEPHONE NO. 915-684-4

APPROVED BY-