

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br><b>30-025-23967</b>   |
| 5. Indicate Type of Lease<br>STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No.  |
| 7. Lease Name or Unit Agreement Name<br><b>Cossatot B</b>   |
| 8. Well No.<br><b>3</b>   |
| 9. Pool name or Wildcat<br><b>Blinebry Oil &amp; Gas</b>  |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)  |

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
**John H. Hendrix Corporation**

3. Address of Operator  
**P. O. Box 3040, Midland, TX 79702-3040**

4. Well Location  
Unit Letter **N** : **330** Feet From The **South** Line and **2080** Feet From The **West** Line  
Section **12** Township **22S** Range **37E** NMPM **Lea** County

|   |   |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |   |
| NOTICE OF INTENTION TO:   | SUBSEQUENT REPORT OF:                               |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input checked="" type="checkbox"/>   |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | ALTERING CASING <input type="checkbox"/>            |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>    |
| OTHER: <input type="checkbox"/>   | PLUG AND ABANDONMENT <input type="checkbox"/>       |
|   | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
|   | OTHER: <input type="checkbox"/>                     |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12/20/96 Set CIBP at 6925' + 20' cement to plug & abandon Wantz  
Granite WASH. Set CIBP at 6250' + 80' cement to plug  
& abandon Brunson Drinkard Abo, S.  
12/23/96 Perf. Blinebry and acidize w/ 2500 gals.  
1/7/97 Testing Blinebry.

Well is now a single Blinebry Oil & Gas producer.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ronnie H. Westbrook TITLE Vice-President DATE 1/8/97  
TYPE OR PRINT NAME Ronnie H. Westbrook (915) TELEPHONE NO. 684-6631

(This space for State Use)  
APPROVED BY JERRY SEXTON  
COMMISSIONER

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JAN 17 1997

SD Brunson Drinkard Abo &  
711 Wantz Granite Wash

