



STATE OF NEW MEXICO
ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
HOBBS DISTRICT OFFICE

July 29, 1997

POST OFFICE BOX 1980
HOBBS, NEW MEXICO 88241-1980
(505) 383-6161

Seely Oil Company
815 West Tenth Street
Fort Worth, Texas 76102

Re: Flour #1-M, Sec. 35, T22S, R37E

Gentlemen:

On June 19, 1997, we received, and I have reviewed, a chart on the above referenced producing well.

A letter dated August 20, 1993, was sent requesting that the well be repaired and re-activated, temporarily abandoned in a proper manner, or plugged and abandoned.

To date, we have not received a sundry notice (C-103), stating any work that may have been done to repair the casing, or your intention regarding the future disposition of the well.

To update our records and to clarify the status of the well, we request that you submit a sundry notice, giving the following information:

1. Date of repairs.
2. String or strings of defective casing.
3. Depth of holes in casing.
4. Method of repair.
5. Volume/sacks of cement required for repairs if this is the method used.
6. If the well is temporarily abandoned, setting depth and type of plug. To receive TA status, you must request same on the C-103.

At the time the sundry notice is received, I will evaluate the information available and determine the proper course of action needed to bring the well into a satisfactory condition.

Page -2-

Very truly yours

OIL CONSERVATION DIVISION

A handwritten signature in cursive script, appearing to read "Chris Williams".

Chris Williams
Supervisor, District I

CW:bp

cc: William J. LeMay
File