

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator <b>Anadarko Production Company</b>		8. Farm or Lease Name <b>E. W. Walden</b>
3. Address of Operator <b>P. O. Box 247, Hobbs, New Mexico 88240</b>		9. Well No. <b>11</b>
4. Location of Well UNIT LETTER <b>M</b> <b>990</b> FEET FROM THE <b>South</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>15</b> TOWNSHIP <b>22S</b> RANGE <b>37E</b> NMPM.		10. Field and Pool, or Wildcat <b>Penrose-Skelly</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3397' GR 3408' RKB</b>		12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Reached TD of 4600' at 10:00 PM 12-11-73.
2. Ran open hole logs.
3. Ran 143 jts 5½" 14# J-55 csg. Set at 4600'. Cemented using 315 sks cl "C" cement. Plug down at 10:00 AM 12-13-73. S I W.O.C.
4. Released the rig.
5. After 24 hrs. pressure tested the casing to 3500 psi for 30 minutes without loss of pressure.
6. SI waiting on well servicing unit to complete.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Joe D. Ramsey</u>	TITLE <b>Area Supervisor</b>	DATE <b>2-6-74</b>
APPROVED BY <u>Joe D. Ramsey</u>	TITLE <u>Dist. L. Supv.</u>	DATE <b>FEB 8 1974</b>
CONDITIONS OF APPROVAL, IF ANY:		