	1			Form C-103	
COPIES RECEIVED	4			Supersedes Old C-102 and C-103	
TRIBUTION		NICEDVATION COMMISSION		Effective 1-1-65	
FE	NEW MEXICO OIL CC	DNSERVATION COMMISSION			
FILE			5a.	Indicate Type of Lease	
U.S.G.S.				State F	ee XX
LAND OFFICE			5.5	State Oil & Gas Lease No	•
OPERATOR					
				11111111111	\overline{m}
DO NOT USE THIS FORM FOR PRI	RY NOTICES AND REPORTS	ON WELLS	51R. 7.	Unit Agreement Name	
OIL XX GAS WELL	OTHER-			Farm or Lease Name	
2. Name of Operator				ВJ	
MILLARD DECK			1	Well No.	
		0.0.2.1		1	
P. O. Box 1047,	Eunice, New Mexico 88	8231		Field and Pool, or Wildo	at
4 Location of Well				Eumont	
UNIT LETTER	660 East	LINE AND	FEST FROM		nnn
	17 TION TOWNSHIP	22S 37E	NMPM.		
South					HHH
THE South LINE, SECT				1111	
THE South LINE, SECT	15. Elevation (Show wh	ether DF, RT, GR, etc.)		County	/////
THE South LINE, SECT	15. Elevation (Show wh			Lea	
	15. Elevation (Show wh	ether DF, RT, GR, etc.)		Lea	
16. Check	15. Elevation (Show wh 3 Appropriate Box To Indica	ether DF, RT, GR, etc.) 3371' GL are Nature of Notice, Re	port or Other	Lea Data	
16. Check	15. Elevation (Show wh	ether DF, RT, GR, etc.) 3371' GL are Nature of Notice, Re		Lea Data	
16. Check	15. Elevation (Show wh 3 A Appropriate Box To Indica INTENTION TO:	ether DF, RT, GR, etc.) 371' GL Ate Nature of Notice, Re SU	port or Other	Lea Data	
16. Check	15. Elevation (Show wh 3 Appropriate Box To Indica	Bether DF, RT, GR, etc.) 371' GL Ate Nature of Notice, Re SU REMEDIAL WORK	PORT OF OTHER	Lea Data EPORT OF:	
16. Check NOTICE OF	15. Elevation (Show wh 3 Appropriate Box To Indica INTENTION TO: PLUG AND ABANDON	Bether DF, RT, GR, etc.) 371' GL Ate Nature of Notice, Re SU REMEDIAL WORK COMMENCE DRILLING OPNS	port or Other BSEQUENT R	Lea Data EPORT OF:	
16. Check NOTICE OF	15. Elevation (Show wh 3 A Appropriate Box To Indica INTENTION TO:	ate Nature of Notice, Re Remedial work commence drilling opns casing test and cement	port or Other BSEQUENT R	Lea Data EPORT OF:	
16. Check NOTICE OF PERFORM REMEDIAL WORK	15. Elevation (Show wh 3 Appropriate Box To Indica INTENTION TO: PLUG AND ABANDON	Bether DF, RT, GR, etc.) 371' GL Ate Nature of Notice, Re SU REMEDIAL WORK COMMENCE DRILLING OPNS	port or Other BSEQUENT R	Lea Data EPORT OF:	
16. Check NOTICE OF PERFORM REMEDIAL WORK	15. Elevation (Show wh 3 A Appropriate Box To Indica INTENTION TO: Plug and abandon change plans	Bether DF, RT, GR, etc.) 3371 GL Bate Nature of Notice, Re SU REMEDIAL WORK COMMENCE DRILLING OPINS CASING TEST AND CEMENT OTHER	port or Other BSEQUENT R	Lea Data EPORT OF: ALTERING CASING PLUG AND ABANDO	

- 1. Drilled 7 7/8" hole to 3950'.
- 2. Ran 123 joints of 5½" J55, 14#, 15.5#, 17# used casing. Set at 3950'. Cemented with 365 sacks Howco Light with 5#'s salt per sack and 200 sacks 50/50 pos and 2% Gel and 5#'s salt per sack. Plug down @ 8:45 PM on 2-15-74.
- After 24 hours pressure tested casing to 2500 psi for 30 minutes without loss of pressure. Released rig at 11PM on 2-16=74.

18. I hereby certify that the information above is true and complete	e to the best of my knowledge and belief.		
	Owner-Operator	DATE February 28,	1974
SIGNED			à
APPROVED BY	TITLE	DATE	