

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- WATER INJECTION		7. Unit Agreement Name NMFU
2. Name of Operator Conoco Inc.		8. Farm or Lease Name SOUTH EUNICE UNIT
3. Address of Operator P. O. Box 460, Hobbs, New Mexico 88240		9. Well No. 64
4. Location of Well UNIT LETTER <u>A</u> <u>660</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>EAST</u> LINE, SECTION <u>33</u> TOWNSHIP <u>22-S</u> RANGE <u>36-E</u> NMPM.		10. Field and Pool, or Wildcat SO. EUNICE 7 RURS. QN.
15. Elevation (Show whether DF, RT, GR, etc.)		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>REPERFORATE &amp; ACIDIZE</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. SPOT 3 BBLs 15% HCL-NE-FE 3500'-  
3770'. PERF w/2 JSPF @ 3619', 39', 54', 57', 75',  
86', 91', 3700', 10', 16', 30', & 3746' (TOTAL 24 PERFS).  
SET PKR @ 3540'. ACIDIZE PERFS w/72 BBLs 15%  
HCL-NE-FE. FLUSH w/21 BBLs 2% KCL TFW.  
REL PKR. SWAB. SET INJECTION PKR @ 3540'.  
PLACE WELL ON INJECTION & MONITOR.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. A. Dyer TITLE Administrative Supervisor DATE 10/12/83

ORIGINAL SIGNED BY EDDIE SEAY  
OIL & GAS INSPECTOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 14 1983  
CONDITIONS OF APPROVAL, IF ANY: