

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

30. Indicate Type of Lease
State ☐ Fee ☒
31. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REFRILL OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER: Dual

2. Name of Operator
Gulf Oil Corp.

3. Address of Operator
P. O. Box 670, Hobbs, NM 88240

4. Location of Well
UNIT LETTER D 810 FEET FROM THE North LINE AND 660 FEET FROM
THE West LINE, SECTION 6 TOWNSHIP 22S RANGE 31E NMPM.

7. Unit Agreement Name

8. Term or Lease Term
H.T. Mattern (WCT-D)

9. Well No.
9

10. Title and Pool, or Wildcat
Jerry
Driskard

11. Elevation (Show whether DF, KT, GR, etc.)
3467' GL

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐

TEMPORARILY ABANDON ☐ COMMENCE DRILLING OPS. ☐ PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐ CHANGE PLANS ☐ CASING TEST AND CEMENT JOBS ☐

OTHER DHC per DHC-546 ☒

SUBSEQUENT REPORT OF:

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH upprod egpt. Pnp acid @ 6100' Swab. Knock CIBP to
bottom. Pnp acid @ 6400' Swab. GIH upprod egpt.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton

TITLE AREA ENGINEER

DATE 6/13/85

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

APPROVED BY

TITLE

DATE

JUN 17 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 14 1985

HC 916 6