

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)		5. Indicate Type of Lease State ☐ Fee ☒ 6. State Oil & Gas Lease No.																
1. OIL WELL ☒ GAS WELL ☐ OTHER ☐ 2. Name of Operator Gulf Oil Corporation 3. Address of Operator Box 670, Hobbs, New Mexico 88240 4. Location of Well UNIT LETTER D 810 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 6 TOWNSHIP 22-S RANGE 37-E NMPM.		7. Unit Agreement Name 8. Farm or Lease Name H. T. Mattern (NCT-D) 9. Well No. 9 10. Field and Pool, or Wildcat Drinkard																
15. Elevation (Show whether DF, RT, GR, etc.) 3467' GL		12. County Lea																
16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data <table border="0"> <tr> <td colspan="2">NOTICE OF INTENTION TO:</td> <td colspan="2">SUBSEQUENT REPORT OF:</td> </tr> <tr> <td>PERFORM REMEDIAL WORK ☐</td> <td>PLUG AND ABANDON ☐</td> <td>REMEDIAL WORK ☐</td> <td>ALTERING CASING ☐</td> </tr> <tr> <td>TEMPORARILY ABANDON ☐</td> <td>CHANGE PLANS ☐</td> <td>COMMENCE DRILLING OPNS. ☐</td> <td>PLUG AND ABANDONMENT ☐</td> </tr> <tr> <td>PULL OR ALTER CASING ☐</td> <td>OTHER ☐</td> <td>CASING TEST AND CEMENT JOBS ☐</td> <td>OTHER ☐</td> </tr> </table> Acidized			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:		PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐	TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐	PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐															
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐															
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	OTHER ☐															
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.																		

6767' PB.

Pumped 3000 gallons of 15% NE HCL acid down tubing over 5-1/2" casing perforations 6433' to 6675'. Flushed with 100 barrels of oil. Maximum pressure 2700#, minimum 2100#, ISIP 1000#, after 3 minutes on vacuum. AIR 4.5 BPM. Returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>D. F. Berlin</u>	TITLE <u>Area Engineer</u>	DATE <u>April 30, 1976</u>
Orig. Signed by Jerry Sexton Dist. 1, Supv.		
APPROVED BY _____	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		

MAY 8 1976

RECEIVED

APR 21 1976

CL CONSERVATION COMM.
10655 N. M.