## N.M. OIL CONS. COMMISSION P.O. BOX 1980

		nos	BBS, NEW MEXICO 88240
Form 3160-5	UNITED	STATES	FORM APPROVED
June 1990)	DEPARTMENT OF		Budget Bureau No. 1004-0135
	BUREAU OF LAND		Expires: March 31, 1993
	BUREAU OF LANE	MANAGEMENT	5. Lease Designation and Serial No.
	CHARRY NOTICES AND	DEDORTS ON WELLS	LC 032573B
	SUNDRY NOTICES AND		6. If Indian, Allottee or Tribe Name
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.			
	Use "APPLICATION FOR PER	RMIT—" for such proposals	
			7 If their or CA Assessment Decision
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
1. Type of Well			
Well Gas Other			8. Well Name and No.
2. Name of Operator	5333-44 B 13 N- 3		
			Elliott B-17 No. 2
3. Address and Telephor	n C	<del></del>	5. Ari well No.
·			30-025-24864
10 Desta Dr. Ste 100W. Midland, TX 79705			10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Blinebry Oil & Gas
770' [] 0 770' []			11. County or Parish, State
330' FNL & 330' FEL			
Sec. 17,	T-22S, R-37E		Lea
<del></del>			<u> </u>
12. CHECI	K APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REPOR	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION			
ITPE U	OF SUBMISSION	TYPE OF ACTION	
Notice Notice	ce of Intent	Abandonment	Charge of Blanc
<b>——</b> 14000	of inten	<b>▽</b> 1 .	Change of Plans
		Recompletion	New Construction
☐ Subse	equent Report	Plugging Back	Non-Routine Fracturing
_		Casing Repair	Water Shut-Off
Final	Abandonment Notice	Altering Casing	Conversion to Injection
		Other	Dispose Water
			(Note: Report results of multiple completion on Well
			Completion or Recompletion Report and Log form )
		nt details, and give pertinent dates, including estimated date of startings for all markers and zones pertinent to this work.)*	any proposed work. If well is directionally drilled
give substitute i	ocations and measured and true vertical deput	s for all markers and zones pertinent to uns work.	
	sed to recomplete this	well to the Blinebry Oil & Gas Poo	ol by the following
procedure:			
1 Set RRP	above Drinkard perfs @	4350'	
2 Perfora	te Blinebry 5436'-5708'	@ 1 isof.	
3. Breakdo	wn perfs with 15% HCl.		
4. Stimula	te Blinebry with 60,000	gals, cross-link fluid and 156,50	00 lbs. 16/30 sand.
5. Clean or	ut sand and put well on	production.	
This wall w	411 ha analystad fam for	A.,	- Dudahand nasalaktan
beneath the		ture downhole commingling with the	- nitukain combitation
beneath the	KBI •		
		X Zura	C (1)
		X Lara	
			9 (T)
			ses (s)
			<u>ئىنىڭ</u>
			<b>c</b> g*)
<u> </u>			<u>.</u>
14. I hereby certify that t	the foregoing is true and correct		
Signed	VIII/Herona	Tide Sr. Conservation Coordinat	or Date 8/4/94
	al or State office use)		
(1 nis space for reder	al or State office use)		
Approved by		Title	Date
Conditions of approve	· · · · · · · · · · · · · · · · · · ·		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECENTO

AUE THEFT

SPICE